

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	140681 KM
File nr. :	1446609	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DRR555 / W0LPD8EW1C8107626 /		yr of constructionr :	2012 / 00
E-File nr. :		First registration :	03/08/2012
VFS-nr. :		Color :	BLACK
Make + Model :	OPEL / ASTRA BREAK	Fuel type :	DIESEL
Object nr. :	67706	Fuel :	
Classification :	O	Environment Class:	EURO 5
Customer company :	EBA	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	ASTRA BRE ecoFLEX Enjoy 150Ys DPF 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1686
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	SEMPERIT	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RL :	[x]	SEMPERIT	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel FR :	[x]	SEMPERIT	Tyre :	[x]	OK	[x]	>6/	Rim :	/
Wheel RR :	[x]	SEMPERIT	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
									[x] SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	H
Rear tyre	215	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT
[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
2	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
4	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	BONNET/CENTER/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
1	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR

Others

HUB CAP FR

			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR				50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
290.08	318.35	30.00	211.80	0	0	0	0	0	0
145.04	159.18	15.00	105.90	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	850.23	0	850.23
HOG: 0	BG: 0		NA Deprec. 425.12
			0.00%
			TOTAL 425.12

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 23/10/2017 Hour : 16:24 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	