

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	102904 KM
<b>File nr. :</b>	1450749	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FSE187 / VF7NX9HD8DY593271 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	08/10/2013
<b>VFS-nr. :</b>		<b>Color :</b>	WHITE
<b>Make + Model :</b>	CITROEN / DS4	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	SMART & CO nv	<b>Co2:</b>	110g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	DS4 BER e-HDi Business GPS 115PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	
<b>Variant car:</b>		<b>Engine size:</b>	1560
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	114	<b>kW:</b>	84
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :		
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	H
Rear tyre	215	60	R	16	H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] REAR DOOR/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
3	0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR	
[x]	REAR LIGHT/RIGHT		HOLE/CRACK/TORN			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
3	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR	
[x]	REAR DOOR/RIGHT/RIGHT		DENT			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
4	15 LU =72.00 EUR	241.34 EUR		50 %	313.34 EUR	
[x]	ROOF/CENTER/RIGHT		DENT		HAGELSCHADE	
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
0	0					
[x]	BONNET/CENTER/RIGHT		DENT		HAGELSCHADE	
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
0	0					
[x]	FRONT MUDGUARD/RIGHT/REAR		DENT		KARAKTERLIJN	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
5	10 LU =48.00 EUR	176.14 EUR		50 %	224.14 EUR	
[x]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
2	0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR	

## Accessories and others

[x] SIDE PROTECTION

BROKEN / CRACKED

	Repair paint - LI	New paint - E	Depr.	Total
3 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

## Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 2	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	22.94 EUR

## Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	REAR LIGHT	72.00 EUR	50 %	72.00 EUR
3	1	CHROOM BAGET	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
22.94	169.44	379.44	313.34	224.14	0	0	0	0	0
22.94	84.72	189.72	156.67	112.07	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
22.94	1086.36	0	<b>1109.30</b>
HOG: 0	BG: 1		NA Deprec. 566.12
			0.00%
			<b>TOTAL 566.12</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 23/10/2017 <b>Hour :</b> 12:30 <b>Company :</b> <b>Executed by VAB Fleet Services</b> <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b>  	