

CZ3D9T

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	100104 KM
File nr. :	1448095	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FEM575 / WDD2042001G138911 /		yr of constructionr :	/
E-File nr. :		First registration :	07/06/2013
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / C	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	127g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	C BRE 180 CDI BlueEFF. S&S 120PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	2143
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	120	kW:	88
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] PIRELLI Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RL : [x] PIRELLI Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] PIRELLI Tyre : [x] OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] PIRELLI Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR BUMPER/SIDE/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/CENTER	DENT

Interior

[x]	SEAT FL	STAIN
-----	---------	-------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	DENT				
		Repair paint - LI	New paint - E	Depr.	Total	
3	40 LU =192.00 EUR	308.20 EUR		50 %	500.20 EUR	
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR	
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE				
	Number	Code	Description	Unit price	Depr.	Total
2	11	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Others

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
4	11	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
0	115.56	818.55	95.00	0	0	0	0	0	0
0	115.56	409.28	95.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
210.56	818.55	0	1029.11
HOG: 0	BG: 0		NA Deprec. 619.84
			0.00%
			TOTAL 619.84

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/10/2017 Hour : 13:01 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	