

D206NK

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: DIRTY [x]
<b>Owner :</b>		<b>Mileage :</b>	65837 KM
<b>File nr. :</b>	1450928	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FEQ198 / WF0KXXGCBKDB65214 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	07/06/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLUE D
<b>Make + Model :</b>	FORD / FOCUS	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	WIRELESS TECHNOLOGIES BVBA	<b>Co2:</b>	88g/km
<b>Driver :</b>		<b>Remote controls:</b>	
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	FOCUS BER EConetic Trend 88g 105PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1560
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	105	<b>kW:</b>	77
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	ANDERE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :		
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :		
Wheel FR :	[x]	ANDERE	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :		
Wheel RES:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :		

  

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] FRONT DOOR/RIGHT/REAR DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR MUDGUARD/LEFT/Front DENT

Number	Code	Description	Unit price	Depr.	Total
4	I1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] REAR MUDGUARD/RIGHT/Front DENT

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x] ROOF STYLE/CENTER/RIGHT DENT

Number	Code	Description	Unit price	Depr.	Total
6	I1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] REAR DOOR/RIGHT/REAR DENT

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] FRONT DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] FRONT MUDGUARD/RIGHT/Front DENT

	Repair paint - LI	New paint - E	Depr.	Total
7 0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] FRONT BUMPER/LEFT DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

### Interior

[x] BACK SHELF MISSING/INCOMPLETE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	0 EUR		50 %	

### Others

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
8 0 LU =0.00 EUR			50 %	

### Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	BACK SHELF	50.00 EUR	50 %	50.00 EUR
Number	Code	Description	Unit price	Depr.	Total
8	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
50.00	322.44	318.35	63.00	626.55	63.00	220.18	30.00	0	0
25.00	216.54	159.18	63.00	313.28	63.00	110.09	15.00	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
236.64	1456.88	0	1693.52
HOG: 0	BG: 0		NA Deprec. 965.08
			0.00%
			TOTAL 965.08

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 23/10/2017 <b>Hour :</b> 15:08 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	