

D2JWVA

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	93676 KM
File nr. :	1450848	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DJV443 / WBAMX11090C975786 /		yr of constructionr :	/
E-File nr. :		First registration :	05/06/2012
VFS-nr. :		Color :	BLUE
Make + Model :	BMW / 5	Fuel type :	DIESEL
Object nr. :	63501	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	MONDELEZ BELGIUM SERVICES BVBA	Co2:	130g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	5 TOURING 520d Start/Stop 163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BREAK	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :			/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/RIGHT	DENT
[x]	ROOF/CENTER/RIGHT	DENT
[x]	FRONT DOOR/RIGHT/REAR	DENT

Interior

[x]	BOOT IN L	CARVED
-----	-----------	--------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
	4	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	WINDSCREEN/LEFT	WINDOW DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
	3	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
	2	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

Pieces

	Number	Code	Description	Unit price	Depr.	Total
	3	1	WIND SCREEN	440.64 EUR	50 %	440.64 EUR

1	2	3	4	5	6	7	8	9	10
0	254.16	560.64	63.00	0	0	0	0	0	0
0	127.08	280.32	63.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	814.80	0	877.80
HOG: 0	BG: 2		NA Deprec. 470.40
			0.00%
			TOTAL 470.40

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 23/10/2017 Hour : 14:58 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	