

D3ZXO4

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	86343 KM
File nr. :	1451967	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1BSO141 / ZFA22500000250130 /		yr of constructionr :	/
E-File nr. :		First registration :	23/08/2011
VFS-nr. :		Color :	WHITE
Make + Model :	FIAT / FIORINO	Fuel type :	DIESEL
Object nr. :	32796	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	ARAMARK SA	Co2:	123g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	FIORINO B/F CARGO PLC Std 75PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	1248
Gear box :	Manueel	Number of places:	2
Number of gears:	5	Number of doors:	5
HP:	75	kW:	55
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	[x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :	OK	[x]	Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	175	70	R	14	T
Rear tyre	175	70	R	14	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/CENTER/LEFT	DENT
[x]	REAR DOOR/CENTER/RIGHT	DENT
[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	WINDSCREEN/CENTER/RIGHT	CHIPS
[x]	FRONT MUDGUARD/RIGHT/CENTER	DENT
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS
[x]	REAR DOOR/LEFT/LEFT	DENT

Interior

[x]	FLOOR BOOT	SCRATCHED
[x]	BOOT IN L	SCRATCHED
[x]	BOOT IN R	SCRATCHED

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/FRONT	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	0 EUR		50 %	
[x]	FRONT DOOR/RIGHT/REAR	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
1	25 LU =120.00 EUR	238.76 EUR		50 %	358.76 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SIDE PROTECTION	10.80 EUR	50 %	10.80 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	SIDE PROTECTION	10.80 EUR	50 %	10.80 EUR

1	2	3	4	5	6	7	8	9	10
380.36	0	0	0	0	0	0	0	0	0
190.18	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	380.36	0	380.36
HOG: 0	BG: 3		NA Deprec. 190.18
			0.00%
			TOTAL 190.18

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/10/2017 Hour : 14:00 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	