

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: EXT: CLEAN [x]
Owner :		Mileage :	91274 KM
File nr. :	1449623	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FEM804 / WBA3K91080F908586 /		yr of constructionr :	/
E-File nr. :		First registration :	07/06/2013
VFS-nr. :		Color :	BROWN
Make + Model :	BMW / 3 TOURING	Fuel type :	DIESEL
Object nr. :	44626	Fuel :	
Classification :	F	Environment Class:	EURO 5
Customer company :	ALSTOM BELGIUM SA (4700001191)	Co2:	123g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 TOURING 316dA 116PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] BRIDGESTONE Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RL : [x] BRIDGESTONE Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] BRIDGESTONE Tyre : [x] OK [x] 4-6/ Rim : / Hubcap :
Wheel RR : [x] BRIDGESTONE Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	16	W
Rear tyre	225	55	R	16	W

Remark : RUNFLAT

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE
- [x] REAR DOOR/LEFT/Front SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] FRONT BUMPER/LEFT/CORNER SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
1	I1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

1	2	3	4	5	6	7	8	9	10
115.56	0	0	0	0	0	0	0	0	0
115.56	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	0	0	115.56
HOG: 0	BG: 0		NA Deprec. 115.56
			0.00%
			TOTAL 115.56

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 23/10/2017 Hour : 15:05 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	