

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	47251 KM
File nr. :	1447472	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
HL8315 / WBAXX110700R37441 /		yr of constructionr :	/
E-File nr. :		First registration :	21/10/2015
VFS-nr. :		Color :	BLUE
Make + Model :	BMW / X4	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	PWC	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	190	kW:	140
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	NOK	[x]	MISSING/INCOMPLETE	
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	NOK	[x]	MISSING/INCOMPLETE
Cert. of reg. copy / Part 2:	NOK	[x]	Insurance certificate :			
Warning vest :			Transport licence :			
Tax certificate :			Navigation CD/SD/DVD			
Fuel card :			Car radio :	OK	[x]	
Mobile phone kit :			Extinguisher :	OK	[x]	
First aid kit :	OK	[x]	Warning triangle :	OK	[x]	
Jack, wheelspanner :			Oil level :	OK	[x]	
			Filled up :	0		

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :		
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :		
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK	/		Rim :	[x]	MISSING/INCOMPLETE	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	17	V
Rear tyre	225	60	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR DOOR/CENTER/RIGHT DENT
- [x] REAR BUMPER/SIDE/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR DOOR/RIGHT/REAR DENT +KRAS RAND
- [x] FRONT DOOR/RIGHT/REAR DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR DOOR/LEFT/FRONT DENT X2

Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	63.00 EUR
3	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR	19.80 EUR
- [x] WINDSCREEN/LEFT WINDOW DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR	58.80 EUR
- [x] FRONT BUMPER/RIGHT/SIDE SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR	115.56 EUR

1	2	3	4	5	6	7	8	9	10
115.56	58.80	82.80	0	0	0	0	0	0	0
115.56	58.80	82.80	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
257.16	0	0	257.16
HOG: 0	BG: 2		NA Deprec. 257.16
			0.00%
			TOTAL 257.16

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/10/2017 Hour : 10:50 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	