

www.vabfleetservices.be Date: 25/10/2017 1/5

D2FXU6

[X] EFFECTIVE [] NOT EXECUTED

[X] COLLECTION

[] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	81144 KM
File nr. :	1450756	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DWL125 / W0LGT8EL	.0D1009089 /	yr of constructionr :	/
E-File nr. :		First registration :	18/09/2012
VFS-nr. :		Color :	BROWN
Make + Model :	OPEL / INSIGNIA BREAK	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification :		Environment Class:	EURO 5
Customer company :	AZO NV	Co2:	119g/km
Driver :		Remote controls:	2
Covering:	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan):	0
Vehicle type :	INSIGNIA BRE ecofl.Cosmo S/S DPF 130PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1956
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	131	kW:	96
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			



www.vabfleetservices.be Date: 25/10/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

	[x]	Width			н	eight	Ì		Type		Rim	Index	
Wheel RES:		Tyre:		OK		/	Rim:				/ Hubcap:		
Wheel RR:		Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:		
Wheel FR:		Tyre:	[x]	OK	[x]	0-1.6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:		
Wheel RL:		Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:		
Wheel FL:		Tyre:		OK	[x]	0-1.6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:		

[x]	Width	Height	Type	Rim	Index
Front tyre	245	45	R	18	W
Rear tyre	245	45	R	18	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 25/10/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

:]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAIN	JT DAMAGE		
-1	NEAR DOWN ENCENTERVEEL 1		SCRITCH WITHTAIL	, Dimilot		
κ]	REAR MUDGUARD/RIGHT/REAR		SCRATCH (WITHOUT	PAINT DAMAGE)	
x]	REAR DOOR/RIGHT/REAR		SCRATCH (WITHOUT	PAINT DAMAGE)	
x]	FRONT DOOR/RIGHT/REAR		SCRATCH (WITHOUT	PAINT DAMAGE)	
x]	FRONT BUMPER/CENTER/RIGHT		SCRATCH WITH PAIN	T DAMAGE		
ST	ATUS: NOT ACCEPTAB	LE				
Во	dywork \& windows					
[x]	REAR DOOR/LEFT/CORNER/BELOW		DENT			
		Repair paint - LI	New paint - E		Depr.	Total
	3 15 LU =72.00 EUR	318.35 EUR			50 %	390.35 EUI
[x]	FRONT THRESHOLD/LEFT/FRONT		DENT			
		Repair paint - LI	New paint - E		Depr.	Total
	2 20 LU =96.00 EUR	310.50 EUR	,		50 %	406.50 EUI
[x]	FRONT MUDGUARD/RIGHT/FRONT		OTHER DAMAGES		SLECHTE HER	STELLING
	Number Code	Description		Unit price	Depr.	Total
	0 0			·	- I	1
nte	erior					
[x]	FLOOR BOOT		STAIN			
	Number Code	Description		Unit price	Depr.	Total
	1 I 1 i-vab-rein-07	CLEANING (PER 15')		14.58 EUR		14.58 EUR
Otł	ners					
	RIM FRONT LEFT					
	Number Code	Description		Unit price	Depr.	Total
	4 I 1 i-vab-herstalu-02	REPAIR ALLOY WHE	EEL	95.00 EUR		95.00 EUR
	RIM FRONT RIGHT					
	Number Code	Description		Unit price	Depr.	Total
		_				



www.vabfleetservices.be Date: 25/10/2017 4/5

1	2	3	4	5	6	7	8	9	10
14.58	406.50	390.35	190.00	0	0	0	0	0	0
14.58	203.25	195.18	190.00	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
1001.43		0	796.85	204.58
603.00	NA Deprec.		BG: 0	HOG: 0
	0.00%			
603.00	TOTAL			



www.vabfleetservices.be Date: 25/10/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMS	STANCES		NORMAL CON	NCLUSION	
Extra Time :	0 min	Waiting time: 0 mi Reason:	n	Towing time : Reason :	0 min
NOT EXECUTED Reason:	: No			I	
Remark :					
Prices in EUR	without VAT				
Authorized by customer :			Executed by VAB Flo	eet Services	
Remark authorized	d customer :				
Date :	25/10/2017	Hour: 13:17			
Company: Executed by VAB Services	Fleet				
E-Mail:	@				
Signature authorized	d by customer				