

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	104301 KM
<b>File nr. :</b>	1448717	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1BXD927 / ZAR94000007110725 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	26/09/2011
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	ALFA ROMEO / GIULIETTA	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	COMPASS GROUP NV	<b>Co2:</b>	114g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	GIULIETTA BER Distinct.Start&Stop 105PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	
<b>Variant car:</b>		<b>Engine size:</b>	1598
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	105	<b>kW:</b>	77
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	DENT	
[x]	REAR DOOR/LEFT/FRONT	DENT	X2
[x]	ROOF/REAR/RIGHT	DENT	
[x]	REAR DOOR/RIGHT/FRONT	DENT	X2
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT MUDGUARD/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR WINDOW/LEFT	WINDOW DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	FRONT BUMPER/LEFT/SIDE	OTHER DAMAGES			NIET GOED GEMONTEERD
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

### Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
3	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
0	24.00	370.00	211.80	380.00	0	0	0	0	0
0	12.00	185.00	105.90	380.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
380.00	605.80	0	<b>985.80</b>
HOG: 0	BG: 0		NA Deprec. <b>682.90</b>
			0.00%
			<b>TOTAL 682.90</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 13/10/2017 <b>Hour :</b> 11:54 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	