

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	66898 KM
File nr. :	1447433	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
HL8323 / WBAXX110300R37422 /		yr of constructionr :	/
E-File nr. :		First registration :	21/10/2015
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / X4	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	PWC	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	XDRIVE 20D	Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	190	kW:	140
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	NOK
Cert. of reg. copy / Part 2:	NOK	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x] PIRELLI	Tyre :	OK [x] 2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x] PIRELLI	Tyre :	OK [x] 2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x] PIRELLI	Tyre :	[x] OK [x] 2-4/	Rim :	/	Hubcap :	
Wheel RR :	[x] PIRELLI	Tyre :	OK [x] 2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]	Tyre :	OK /	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	17	V
Rear tyre	225	60	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK /	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] FRONT DOOR/RIGHT/CENTER DENT
- [x] BONNET/CENTER/LEFT/FRONT CHIPS

Interior

- [x] CENTER CONSOLE SCRATCHED

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 2		NA Deprec. 0
			0.00%
			TOTAL 0

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 10/10/2017 Hour : 11:49 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	