

www.vabfleetservices.be Date: 25/10/2017 1/4

D5VCZ3

[X] EFFECTIVE [] NOT EXECUTED [] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness:	INT: DIRTY [x] EXT: CLEAN [x]
Owner:		Mileage :	57329 KM
File nr. :	1453432	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1JEZ319 / WBA3Y11000D451	1204 /	yr of constructionr :	/
E-File nr. :		First registration :	28/11/2014
VFS-nr. :		Color :	BROWN
Make + Model :	BMW / 3 GT	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel:	
Classification:		Environment Class:	EURO 6
Customer company:	ONBEKEND	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes			
Variant car:		Engine size:	1995			
Gear box :	Manueel	Number of places:	5			
Number of gears:	6	Number of doors:	5			
нр:	136	kW:	100			
Fisc HP		Imported vehicle:				
Animals transported:	No	Smoked in vehicle:	No			
Due date vehicle inspection:		Extra set of tires:	No			
		Use:	Unknown			
General condition:						



www.vabfleetservices.be Date: 25/10/2017 2/4

Original registr. number :	OK		Service manual :		
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

		[x]	Width		Height		Туре	Riı	m	Index
Wheel RES:	[x]	ANDERE	Tyre :	OK	/	Rim:		/ Hul	bcap :	
Wheel RR:	[x]	MICHELIN	Tyre:	OK	[x] 2-4/	Rim:		/ Hul	bcap :	
Wheel FR:	[x]	MICHELIN	Tyre: [x	K] OK	[x] 4-6/	Rim:		/ Hul	bcap :	
Wheel RL:	[x]	MICHELIN	Tyre:	OK	[x] 2-4/	Rim:		/ Hul	bcap :	
Wheel FL:	[x]	MICHELIN	Tyre:	OK	[x] 4-6/	Rim:		/ Hul	bcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	Y
Rear tyre	225	55	R	17	Y

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 25/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] WINDSCREEN/CENTER/RIGHT CHIPS

[x] BONNET/CENTER/LEFT/FRONT CHIPS

[x] REAR DOOR/LEFT/LEFT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/RIGHT/CORNER SCRATCH WITH PAINT DAMAGE

 Repair paint - LI
 New paint - E
 Depr.
 Total

 2 0 LU = 0.00 EUR
 254.16 EUR
 50 %
 254.16 EUR

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		14.58 EUR

1	2	3	4	5	6	7	8	9	10
14.58	254.16	0	0	0	0	0	0	0	0
14.58	127.08	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
268.74	0	254.16	14.58
NA Deprec. 141.66		BG: 2	HOG: 0
0.00%			

0.00%
TOTAL 141.66



www.vabfleetservices.be Date: 25/10/2017 4/4

[x] = Status Modification

Pictures: No

rictures: No							
CIRCUMS	TANCES		NORMAL CONCLUSION				
Extra Time :	0 min	Waiting time: 0 min Reason:	1	Towing time : Reason :	0 min		
NOT EXECUTED : Reason :	No	I					
Remark:							
Prices in EUR w	rithout VAT						
Authorized by customer:			Executed by VAB Fleet Se	ervices			
Remark authorized	customer :						
Date :	25/10/2017	Hour: 13:39					
Company:							
Executed by VAB FI Services	leet						
E-Mail :	@						
Signature authorized l	by customer						