

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	60781 KM
File nr. :	1449131	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1JXJ936 / VF30E9HD8FS018673 /		yr of constructionr :	/
E-File nr. :		First registration :	12/03/2015
VFS-nr. :		Color :	BLACK
Make + Model :	PEUGEOT / 5008	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	113g/km
Driver :		Remote controls:	1
Covering :	LEATHER	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1560
Gear box :	Automaat algemeen	Number of places:	7
Number of gears:		Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	NOK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	[x]
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]	Tyre :	OK	[x]	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	H
Rear tyre	215	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE
[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE		+DEUKEN	
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x]	FRONT THRESHOLD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE		+DEUK	
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	310.50 EUR			310.50 EUR

1	2	3	4	5	6	7	8	9	10
211.80	308.20	310.50	0	0	0	0	0	0	0
105.90	154.10	310.50	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	830.50	0	830.50
HOG: 0	BG: 0		NA Deprec. 570.50
			0.00%
			TOTAL 570.50

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/10/2017 Hour : 14:07 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	