

www.vabfleetservices.be Date: 06/10/2017 1/5

CU5KB3

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

commissionar :	KBC REMARKETING	Cleaniness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	104253 KM
File nr. :	1444296	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EAK203 / WBA1N310X0J03	0393 /	yr of constructionr :	/
E-File nr. :		First registration :	03/10/2012
VFS-nr. :		Color :	BLUE
Make + Model :	BMW / 1	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification:		Environment Class:	EURO 5
Customer company :	KBC BANK NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	1 SPORTSHATCH 116d Eff.Dyn.Ed.116PK	Country registration :	BELGIUM

Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Metallic paint:

Yes



www.vabfleetservices.be Date: 06/10/2017 2/5

Original registr. number : OK Service manual : [x] Cert. of conformity: Cert. of reg. / Part 1: OK Insurance certificate: Cert. of reg. copy / Part 2: OK [x]Transport licence: Warning vest: Tax certificate: Navigation CD/SD/DVD Fuel card : Car radio: OK [x] Extinguisher: Mobile phone kit : OK [x] Warning triangle: OK [x] Oil level: OK OK First aid kit: [x] [x] Filled up: 0 Jack, wheelspanner : [x]

Wheels and tyres: Summer tires

I		[17]	Width		ш	night.			Tyme	Dim	Indov
Wheel RES:	[x]	MICHELIN	Tyre:	OK		/	Rim:			/ Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre: [x	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:	
Wheel RL:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:	
Wheel FL:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	W
Rear tyre	205	55	R	16	W

Remark: REPSET OK

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 06/10/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

FRONT BUMPER/LEFT/CORNER

2 0 LU =0.00 EUR

[x]

<u> </u>	ATUS: ACCEPTABLE	USAGE DAMA	<u> </u>					
Во	dywork \& windows							
[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH	H PAINT DAMAGE				
[x]	REAR BUMPER/CENTER/RIGHT		SCRATCH WITH	H PAINT DAMAGE				
[x]	REAR MUDGUARD/LEFT/CENTER		SCRATCH (WIT	THOUT PAINT DAMAGE	E)			
x]	REAR MUDGUARD/RIGHT/FRONT		DENT					
[x]	ROOF/CENTER/LEFT		DENT					
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITI	H PAINT DAMAGE					
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH WITH	H PAINT DAMAGE					
[x]	BONNET/CENTER/RIGHT	DENT						
[x]	BONNET/CENTER/RIGHT/FRONT	DENT	DENT					
Inte	erior							
[x]	FLOOR FL		HOLE					
[x]	CARPET FL		HOLE					
ST	ATUS: NOT ACCEPTAE	LE						
Во	dywork \& windows							
[x]	REAR MUDGUARD/RIGHT/CENTER		DENT					
	Number Code	Description		Unit price	Depr.	Total		
	4 I 1 i-vab-uitd-01	BEAT OUT DENT		63.00 EUR	1	63.00 EUR		
[x]	FRONT DOOR/LEFT/FRONT		DENT					
	Number Code	Description		Unit price	Depr.	Total		
	3 I 1 i-vab-uitd-01	BEAT OUT DENT		63.00 EUR		63.00 EUR		

SCRATCH WITH PAINT DAMAGE

New paint - E

Repair paint - LI

211.80 EUR

MEERDERE

Depr.

50 %

Total

211.80 EUR



www.vabfleetservices.be Date: 06/10/2017 4/5

Interior

[x] SEAT FR STAIN

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

	1	2	3	4	5	6	7	8	9	10
	14.58	211.80	63.00	63.00	0	0	0	0	0	0
Γ	14.58	105.90	63.00	63.00	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
352.38		0	211.80	140.58
246.48	NA Deprec.		BG: 0	HOG: 0
	0.00%			
246.48	TOTAL			



www.vabfleetservices.be Date: 06/10/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time :	0 min	Waiting time	e: 0 min		Towing time :	0 min	
		Reason:			Reason:		
NOT EXECUTED :	No				<u> </u>		
	NO						
Reason:							
Remark:							
Prices in EUR wit	hout VAT						
Authorized by customer :				Executed by VAB Fleet Se	ervices		
customer .							
Remark authorized cu	stomer :						
Date :	06/10/2017	Hour:	10:45				
Company :							
Executed by VAB Flee Services	t						
E-Mail :	@						
Signature authorized by	quotomor						
- Signature authorized by	customer		_				