

www.vabfleetservices.be Date: 23/10/2017 1/4

D43AH4

[X] EFFECTIVE [] NOT EXECUTED [] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: DIRTY [x] EXT: CLEAN [x] Owner: Mileage : 62179 KM File nr. : Mileage start / arrival: 0 / 01452042 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1JHT486 / WDD1760081V047211 / E-File nr. : First registration: 23/12/2014 Color: VFS-nr.: **GREY** Make + Model : Fuel type : MERCEDES / A **DIESEL** Object nr. : Fuel: **ONBEKEND** Classification: **Environment Class:** EURO 6 N Customer company: Co2: **ONBEKEND** 114g/km Driver : Remote controls: 2 TISSUE-LEATHER Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type : Country registration: **BELGIUM**

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	2143
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	



www.vabfleetservices.be Date: 23/10/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRI	DGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RL:	[x]	BRII	DGESTONE	Tyre:		OK	[x]	4-6 /	Rim:				/ Hubcap:	
Wheel FR:	[x]	BRII	DGESTONE	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RR:	[x]	BRII	DGESTONE	Tyre:		OK	[x]	4-6 /	Rim:				/ Hubcap:	
Wheel RES:	[x]			Tyre:		OK		/	Rim:				/ Hubcap:	
		[x]	W	idth	Ì		He	eight			Туре		Rim	Index
Fron	t tyre			225			4	45			R		17	V
Rea	r tvre			225				45			R		17	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 23/10/2017 3/4

STATUS: NOT ACCEPTABLE

			1							
CLEANI	LINESS INTERIOR									
Number	Code		Description			Unit price	Depr.		Tota	
1 I 2	specifiek-per-kwar	tier-a-vab-rein-03	CLEANING	INTERIOR		14.58 EUR	ı		29.16 E	
RIM FR	ONT LEFT									
Number	Code		Description			Unit price	Depr.		Tota	
2 I 1	i-vab-herstalu-02		REPAIR AL	LOY WHEEL		95.00 EUR			95.00 E	
RIM FRO	ONT RIGHT		Description			Unit price	Depr.		Tota	
2 I 1	i-vab-herstalu-02		REPAIR AL	LOY WHEEL		95.00 EUR	95.00 EUR			
1	2	3	4	5	6	7	8	9	10	
29.16	190.00	0	0	0	0	0	0	0	0	
29.16	190.00	0	0	0	0	0	0	0	0	
INNO	VATIVE	TRADITI	ONAL	G	ENERAL					
219.16 0		0								

0.00% TOTAL

219.16



Date: 23/10/2017 www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	FANCES		NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time: 0 n Reason:	nin	Towing time : Reason :	0 min			
NOT EXECUTED : Reason :	No	I		<u> </u>				
Remark :								
Prices in EUR w	rithout VAT							
Authorized by customer:			Executed by VAB Fleet S	ervices				
Remark authorized	customer :							
Date :	23/10/2017	Hour: 07:20						
Company : Executed by VAB Fl Services	eet							
E-Mail :	@							
Signature authorized l	by customer							