

www.vabfleetservices.be Date: 13/10/2017 1/5

CZMQ17

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Vehicle type:

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 187628 KM File nr. : Mileage start / arrival: 0 / 01448487 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1GHS479 / VF38E9HD8EL005556 / E-File nr. : First registration: 11/02/2014 Color: VFS-nr.: **BLACK** Make + Model : Fuel type : PEUGEOT / 508 BREAK **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Α Customer company: Co2: **EDF LUMINUS** 110g/km Driver : Remote controls: 1 TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0

Country registration:

BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			



www.vabfleetservices.be Date: 13/10/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	NOK	[x]	Insurance certificate :		
Warning vest:			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

heel RR :	[x]	MICHELIN	Tyre : Tyre :		OK OK	[x]	1.6-2 /	Rim :	[x]	WHEEL SCRATCHED)	/ Hubcap : / Hubcap :	
		[x]	Width	$\overline{}$		Н	eight	ĺ		Туре		Rim	Index
Fron	t tyre	[x]	Width 215	\exists			e ight	-		Type R			Index H

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



13/10/2017 www.vabfleetservices.be Date: 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

Во	dywork \& windows		
[x]	REAR MUDGUARD/LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	
[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR BUMPER/RIGHT/CORNER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR WINDOW STYLE/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR THRESHOLD/LEFT/REAR	DENT	INT
[x]	REAR DOOR/RIGHT/CENTER	DENT	
[x]	FRONT MUDGUARD/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS	
[x]	REAR DOOR/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE	
Inte	erior		

[x] DOOR IN REAR L SCRATCHED

BOOT LID IN SCRATCHED

STATUS: NOT ACCEPTABLE

Others

RIM FRONT RIGHT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
95.00	0	0	0	0	0	0	0	0	0
95.00	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
95.00	0	0	95.00
NA Deprec. 95.00		BG: 0	HOG: 0
0.00%			

TOTAL 95.00



www.vabfleetservices.be Date: 13/10/2017 4/5



www.vabfleetservices.be Date: 13/10/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMS	CIRCUMSTANCES				UNDER CONDITION - VEHICLE WET				
Extra Time :	0 min	Waiting time	Waiting time: 0 min		Towing time :	0 min			
		Reason:			Reason :				
NOT EXECUTED	: No	I							
Reason :									
Remark :									
Prices in EUR	without VAT								
Authorized by customer:				Executed by VAB	Fleet Services				
Remark authorized	d customer :								
Date :	13/10/2017	Hour:	11:09						
Company:									
Executed by VAB l Services	Fleet								
E-Mail :	@								
Signature authorized	l by customer								
	/								