

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	79977 KM
File nr. :	1448054	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DGA956 / WBAVP31070VT06680 /		yr of constructionr :	/
E-File nr. :		First registration :	08/05/2012
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / X1	Fuel type :	DIESEL
Object nr. :	53983	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	LELEUX ASSOCIATED BROKER NV	Co2:	164g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	X1 xDrive20 177PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	177	kW:	130
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x] WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	[x] WHEEL SCRATCHED / Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	H
Rear tyre	225	50	R	17	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)

Interior

[x] DASHBORD OTHER DAMAGES

[x] SEAT FL OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
5 10 LU =48.00 EUR	211.80 EUR		50 %	259.80 EUR

[x] REAR MUDGUARD/RIGHT/REAR DENT

	Repair paint - LI	New paint - E	Depr.	Total
5 50 LU =240.00 EUR	0 EUR	403.51 EUR	50 %	643.51 EUR

[x] REAR DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 15 LU =72.00 EUR	318.35 EUR		50 %	390.35 EUR

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

[x] REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] FRONT DOOR/RIGHT/REAR DENT

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] BONNET/LEFT/CENTER DENT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x]	FRONT BUMPER/RIGHT		HOLE/CRACK/TORN		
		Repair paint - LI	New paint - E	Depr.	Total
2	20 LU =96.00 EUR	0 EUR	235.80 EUR	50 %	331.80 EUR

Interior

[x]	BOOT IN L		CUT / TORN		
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

[x]	BOOT IN R		CUT / TORN		
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	BEKLEDING	80.00 EUR	50 %	80.00 EUR

Number	Code	Description	Unit price	Depr.	Total
1	1	BEKLEDING	80.00 EUR	50 %	80.00 EUR

Number	Code	Description	Unit price	Depr.	Total
2	1	FRONT BUMPER	403.20 EUR	50 %	403.20 EUR

Number	Code	Description	Unit price	Depr.	Total
5	1	FENDER REAR RIGHT	588.00 EUR	50 %	588.00 EUR

1	2	3	4	5	6	7	8	9	10
208.00	735.00	63.00	500.99	1809.66	318.35	95.00	0	0	0
104.00	367.50	63.00	305.82	904.83	159.18	95.00	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
268.64	3461.36	0	3730.00
HOG: 0	BG: 0		NA Deprec. 1999.32
			0.00%
			TOTAL 1999.32

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 20/10/2017 Hour : 11:17 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	