

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	160451 KM
File nr. :	1450024	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EGT747 / W0LPE6EW3DG015829 /		yr of constructionr :	/
E-File nr. :		First registration :	28/11/2012
VFS-nr. :		Color :	BLACK
Make + Model :	OPEL / ASTRA	Fuel type :	DIESEL
Object nr. :	75932	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	GAMSYS SOFTWARE	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	ASTRA BER ecoFLEX Cosmo St/St 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:		Engine size:	1686
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :			/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :			/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	[x]	>6/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	V
Rear tyre	225	50	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR DOOR/LEFT/Front SCATCH WITH PAINT DAMAGE
- [x] REAR DOOR/RIGHT/REAR SCATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR BUMPER /LEFT/CORNER SCATCH WITH PAINT DAMAGE

		Repair paint - LI	New paint - E	Depr.	Total
5	15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR

- [x] REAR THRESHOLD/LEFT/REAR DENT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR	50 %	115.56 EUR

- [x] REAR DOOR/RIGHT/Front DENT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

- [x] FRONT MUDGUARD/LEFT/CENTER SCATCH WITH PAINT DAMAGE

		Repair paint - LI	New paint - E	Depr.	Total
3	10 LU =48.00 EUR	220.18 EUR		50 %	268.18 EUR

Interior

- [x] BOOT LID IN CARVED

		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Accessories and others

- [x] SIDE PROTECTION BROKEN / CRACKED

		Repair paint - LI	New paint - E	Depr.	Total
5	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4 personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR		45.88 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	UPHOLSTERY DOOR	90.00 EUR	50 %	90.00 EUR

Number	Code	Description	Unit price	Depr.	Total
5	1	CHROOM BAGET	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
159.88	115.56	268.18	63.00	186.00	95.00	0	0	0	0
102.88	57.78	134.09	63.00	93.00	95.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
319.44	568.18	0	887.62
HOG: 0	BG: 0		NA Deprec. 545.75
			0.00%
			TOTAL 545.75

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 23/10/2017 Hour : 09:08 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	