

COWX67

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	61184 KM
File nr. :	1440173	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GTJ673 / JTMZHREVVX0D018586 /		yr of constructionr :	/
E-File nr. :		First registration :	24/04/2014
VFS-nr. :		Color :	BLACK
Make + Model :	TOYOTA / RAV4	Fuel type :	DIESEL
Object nr. :	39269	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	TOYOTA MOTOR EUROPE	Co2:	127g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	3 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1998
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	124	kW:	91
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:	EURO 5B		

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	NOK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]	ANDERE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	65	R	17	WINTER T
Rear tyre	225	65	R	17	WINTER T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE		
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE		
[x]	FRONT DOOR/LEFT/FRONT	DENT		
[x]	FRONT MUDGUARD/LEFT/CENTER	DENT	2X	
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS		
[x]	FRONT BUMPER/CENTER/RIGHT	DENT		
[x]	REAR DOOR/LEFT/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT/LEFT	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FRONT	28.80 EUR	50 %	28.80 EUR

1	2	3	4	5	6	7	8	9	10
52.80	0	0	0	0	0	0	0	0	0
26.40	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	52.80	0	52.80
HOG: 0	BG: 0		NA Deprec. 26.40
			0.00%
			TOTAL 26.40

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 22/09/2017 Hour : 09:48 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	