

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	89837 KM
File nr. :	1447945	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FNT688 / VF7UA9HR8DJ735257 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	02/09/2013
VFS-nr. :		Color :	RED
Make + Model :	CITROEN / C4 GRANDE PICASSO	Fuel type :	DIESEL
Object nr. :	176	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SOLVAY SA	Co2:	120g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GR.C4 PICASSO 7pl.Excl.BMP FAP 112PK Aut	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1560
Gear box :	Automaat algemeen	Number of places:	7
Number of gears:		Number of doors:	5
HP:	112	kW:	82
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK
Cert. of reg. / Part 1: OK	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate : OK
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner :	Oil level : OK
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	FIRESTONE	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel RL :	FIRESTONE	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel FR :	FIRESTONE	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel RR :	FIRESTONE	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel RES:	ANDERE	Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/RIGHT	DENT	
[x]	REAR THRESHOLD/LEFT/REAR	DENT	INTERIEUR
[x]	REAR THRESHOLD/RIGHT/REAR	DENT	INTERIEUR
[x]	ROOF STYLE/FRONT/LEFT/CENTER	OTHER DAMAGES	VLEK
[x]	ROOF STYLE/FRONT/RIGHT/CENTER	OTHER DAMAGES	VLEK
[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec. 0
			0.00%
			TOTAL 0

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 20/10/2017 Hour : 09:50 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	