

www.vabfleetservices.be Date: 25/10/2017 1/5

D1LCGP

#### [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	22791 KM
File nr. :	1450053	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LRX615 / ZFA3120000J5006	571 /	yr of constructionr :	/
E-File nr. :		First registration :	18/11/2015
VFS-nr. :		Color :	RED
Make + Model :	FIAT / 500	Fuel type :	PETROL
Object nr. :	42718	Fuel:	
Classification:		Environment Class:	EURO 6
Customer company:	COMMISSIE VOOR REGULERING VAN ELECTRICIT	Co2:	99g/km
Driver :		Remote controls:	1
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan):	0
Vehicle type :		Country registration :	BELGIUM

Variant car:		Engine size:	875
Gear box :	Manueel	Number of places:	4
Number of gears:	6	Number of doors:	3
нр:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:	,	1	

Metallic paint:

No



www.vabfleetservices.be Date: 25/10/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]	
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	NOK	[x] MISSING/INCOMPLETE	
Cert. of reg. copy / Part 2:			Insurance certificate :			
Warning vest :	OK	[x]	Transport licence :			
Tax certificate :		Navigation CD/SD/DVD				
Fuel card :			Car radio :	OK	[x]	
Mobile phone kit :			Extinguisher :	OK	[x]	
			Warning triangle :	OK	[x]	
First aid kit :	OK	[x]	Oil level :	OK	[x]	
Jack, wheelspanner :		[x]	Filled up :	0		

#### Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre:	OK	[x] 4-6/	Rim:				Hubcap:	
Wheel RL:	[x]	CONTINENTAL	Tyre:	OK	[x] 4-6/	Rim:	[x]	WHEEL SCRATCHED	)	Hubcap:	
Wheel FR:	[x]	CONTINENTAL	Tyre:	x] OK	[x] 4-6/	Rim:	[x]	WHEEL SCRATCHED	)	Hubcap:	
Wheel RR:	[x]	CONTINENTAL	Tyre:	OK	[x] 4-6/	Rim:	[x]			Hubcap:	
Wheel RES:	[x]	ANDERE	Tyre:	OK	/	Rim:				Hubcap:	
				•							1
		[x] W	ldth/		Height			Type		Rim	Index

[x]	Width	Height	Type	Rim	Index
Front tyre	195	45	R	16	Н
Rear tyre	195	45	R	16	Н

Remark:

#### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 25/10/2017 3/5

#### STATUS: ACCEPTABLE / USAGE DAMAGE

Bod	ywork \& windows					
x]	BONNET/CENTER/RIGHT/FRONT		CHIPS			
<b>(</b> ]	FRONT BUMPER/LEFT		SCRATCH WITH PAIN	IT DAMAGE		
κ]	REAR DOOR/LEFT/LEFT		DENT			
STA	ATUS: NOT ACCEPTAB	LE				
Bod	ywork \& windows					
κ]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAIN	IT DAMAGE		
		Repair paint - LI	New paint - E		Depr.	Total
	0 LU =0.00 EUR	169.44 EUR			50 %	169.44 EUR
κ]	REAR DOOR/CENTER/LEFT		DENT			
	Number Code	Description		Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT		63.00 EUR		63.00 EUR
:]	WINDSCREEN/CENTER/RIGHT		WINDOW DAMAGE			
	Number Code	Description		Unit price	Depr.	Total
:	5 I 1 i-vab-herstr-01	WINDOW REPAIR		58.80 EUR	,	58.80 EUR
λcc	essories and others					
x]	OUTSIDE MIRROR RIGHTHAND SIDE		OTHER DAMAGES			
	Number Code	Description		Unit price	Depr.	Total
	3 I 1 i-vab-sp-01	SPOTREPAIR		115.56 EUR		115.56 EUR
Oth	ers					
	RIM REAR LEFT					
	Number Code	Description		Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHI	EEL	95.00 EUR	1	95.00 EUR
	RIM FRONT RIGHT					
	Number Code	Description		Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHI	EEL	95.00 EUR		95.00 EUR



www.vabfleetservices.be Date: 25/10/2017 4/5

1	2	3	4	5	6	7	8	9	10
169.44	63.00	115.56	190.00	58.80	0	0	0	0	0
84.72	63.00	115.56	190.00	58.80	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
596.80		0	169.44	427.36
512.08	NA Deprec.		BG: 1	HOG: 0
	0.00%			
512.08	TOTAL			



www.vabfleetservices.be Date: 25/10/2017 5/5

[x] = Status Modification

**Pictures:** No

Tietales : 1								
CIRCUMS	STANCES		NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time: 0 : Reason:	min	Towing time : Reason :	0 min			
NOT EXECUTED Reason:	: No							
Remark :								
Prices in EUR	without VAT							
Authorized by customer :			Executed by VAB Fle	et Services				
Remark authorized	l customer :							
Date : Company :	25/10/2017	<b>Hour:</b> 11:35						
Executed by VAB I Services	Fleet							
E-Mail:	@							
Signature authorized	l by customer		_					