

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	9601 KM
File nr. :	1452800	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1PNK827 / VF1FW18B556139663 /		yr of constructionr :	/
E-File nr. :		First registration :	11/08/2016
VFS-nr. :		Color :	WHITE
Make + Model :	RENAULT / KANGOO	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	1461
Gear box :	Manueel	Number of places:	2
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]	MICHELIN	Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT DOOR/LEFT/REAR DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT		DENT			
	Number	Code	Description	Unit price	Depr.	Total
	4	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT		DENT			
			Repair paint - LI	New paint - E	Depr.	Total
	1	0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR
[x]	REAR DOOR/RIGHT/CENTER		DENT			
			Repair paint - LI	New paint - E	Depr.	Total
	1	0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR
[x]	WINDSCREEN/LEFT		HOLE/CRACK/TORN			
			Repair paint - LI	New paint - E	Depr.	Total
	3	0 LU =0.00 EUR	0 EUR		50 %	
			Repair paint - LI	New paint - E	Depr.	Total
	3	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	FRONT DOOR/RIGHT/CENTER		DENT			
			Repair paint - LI	New paint - E	Depr.	Total
	1	0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT		DENT			
			Repair paint - LI	New paint - E	Depr.	Total
	2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
Pieces						
	Number	Code	Description	Unit price	Depr.	Total
	3	1	WIND SCREEN	275.40 EUR	50 %	275.40 EUR

1	2	3	4	5	6	7	8	9	10
708.67	63.00	395.40	110.64	0	0	0	0	0	0
354.34	63.00	197.70	110.64	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
173.64	1104.07	0	1277.71
HOG: 0	BG: 3		NA Deprec. 725.68
			0.00%
			TOTAL 725.68

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 24/10/2017 Hour : 14:23 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	