

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: DIRTY [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 184836 KM |
| File nr. : | 1447710 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1GSC441 / VF1KZ0R0250519853 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 14/04/2014 |
| VFS-nr. : | | Color : | WHITE |
| Make + Model : | RENAULT / MEGANE BREAK | Fuel type : | DIESEL |
| Object nr. : | 66198 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | CEGELEC INFRA TECHNICS | Co2: | 105g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1461 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 95 | kW: | 70 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |
| General condition: | | | |

| | | | | | |
|------------------------------|----|-------------------------|-----------------------|-----|-----|
| Original registr. number : | OK | Service manual : | OK | [x] | |
| Cert. of reg. / Part 1: | OK | [x] | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | | | |
| Warning vest : | OK | [x] | Transport licence : | | |
| Tax certificate : | | Navigation CD/SD/DVD | OK | [x] | |
| Fuel card : | | Car radio : | OK | [x] | |
| Mobile phone kit : | | Extinguisher : | OK | [x] | |
| First aid kit : | OK | [x] | Warning triangle : | OK | [x] |
| Jack, wheelspanner : | | Oil level : | OK | [x] | |
| | | Filled up : | 0 | | |

Wheels and tyres: Summer tires

| | | | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|------|-------|-------|----------|---------------|---------------|
| Wheel FL: | [x] | FULDA | Tyre : | OK | [x] | >6/ | Rim : | / | Hubcap : | | |
| Wheel RL : | [x] | GOODYEAR | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : | | |
| Wheel FR : | [x] | FULDA | Tyre : | [x] | OK | [x] | >6/ | Rim : | / | Hubcap : | [x] SCRATCHED |
| Wheel RR : | [x] | GOODYEAR | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : | [x] SCRATCHED | |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | / | Hubcap : | | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205 | 55 | R | 16 | H |
| Rear tyre | 205 | 55 | R | 16 | H |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|--|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | |
|-----|------------------------------|--------------------------|---------------------------|--------------|--------------|
| [x] | REAR BUMPER/SIDE/RIGHT/FRONT | | SCRATCH WITH PAINT DAMAGE | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 4 | 0 LU =0.00 EUR | 211.80 EUR | | 50 % | 211.80 EUR |
| [x] | REAR MUDGUARD/RIGHT/FRONT | | SCRATCH WITH PAINT DAMAGE | +DEUK | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 4 | 0 LU =0.00 EUR | 308.20 EUR | | 50 % | 308.20 EUR |
| [x] | REAR DOOR/RIGHT/REAR | | SCRATCH WITH PAINT DAMAGE | +DEUK | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 4 | 0 LU =0.00 EUR | 318.35 EUR | | 50 % | 318.35 EUR |
| [x] | REAR DOOR/RIGHT/CENTER | | SCRATCH WITH PAINT DAMAGE | +DEUK | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 0 | 0 | | | | |
| [x] | BONNET/CENTER/RIGHT/FRONT | | SCRATCH WITH PAINT DAMAGE | +DEUK | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 3 | 0 LU =0.00 EUR | 290.08 EUR | | 50 % | 290.08 EUR |
| [x] | FRONT BUMPER/CENTER/RIGHT | | OTHER DAMAGES | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 10 LU =48.00 EUR | 0 EUR | | 50 % | 48.00 EUR |

Others

CLEANLINESS INTERIOR

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|--------------------------------------|-------------------|-----------|-----------|
| 5 | I 5 | specifiek-per-kwartier-a-vab-rein-03 | CLEANING INTERIOR | 14.58 EUR | 72.90 EUR |

HUB CAP REAR RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|--------------|------------|-------|-------|
| 1 | 0 | LU =0.00 EUR | | 50 % | |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 1 | 1 | WHEEL CAP | 30.00 EUR | 50 % | 30.00 EUR |

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 1 | 1 | WHEEL CAP | 30.00 EUR | 50 % | 30.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|-------|--------|--------|-------|---|---|---|---|----|
| 60.00 | 48.00 | 290.08 | 838.35 | 72.90 | 0 | 0 | 0 | 0 | 0 |
| 30.00 | 24.00 | 145.04 | 419.18 | 72.90 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 72.90 | 1236.43 | 0 | 1309.33 |
| HOG: 0 | BG: 0 | | NA Deprec. 691.12 |
| | | | 0.00% |
| | | | TOTAL 691.12 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 24/10/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |