

D1LYCJ

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	98673 KM
<b>File nr. :</b>	1450063	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FQF922 / WVGZZZ1TZEW011161 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	23/09/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLUE
<b>Make + Model :</b>	VOLKSWAGEN / TOURAN	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	74419	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	BRUSSELS AIRPORT COMPANY NV	<b>Co2:</b>	121g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	TOURAN Trendline BMT Start/Stop 105PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1598
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	105	<b>kW:</b>	77
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :		/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :
Wheel RES:	[x]	MICHELIN	Tyre :	OK		/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR DOOR/RIGHT/REAR DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] REAR MUDGUARD/RIGHT/REAR DENT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] BONNET/CENTER/RIGHT OTHER DAMAGES ISOLATIE

	Repair paint - LI	New paint - E	Depr.	Total
1 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

[x] FRONT/RIGHT HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
2 10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

### Interior

[x] BOOT LID IN CARVED

	Repair paint - LI	New paint - E	Depr.	Total
1 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

### Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1 BEKLEDING		50.00 EUR	50 %	50.00 EUR

Number	Code	Description	Unit price	Depr.	Total
1	1 ISOLATIE		50.00 EUR	50 %	50.00 EUR

Number	Code	Description	Unit price	Depr.	Total
2	1 FRONT		28.80 EUR	50 %	28.80 EUR

1	2	3	4	5	6	7	8	9	10
148.00	76.80	211.80	63.00	95.00	0	0	0	0	0
74.00	38.40	105.90	63.00	95.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
158.00	436.60	0	594.60
HOG: 0	BG: 0		NA Deprec. 376.30
			0.00%
			TOTAL 376.30

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 18/10/2017 <b>Hour :</b> 10:10 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	