

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	125525 KM
File nr. :	1452552	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DQL868 / U5YHC816ACL213379 /		yr of constructionr :	/
E-File nr. :		First registration :	24/07/2012
VFS-nr. :		Color :	GREY
Make + Model :	KIA / CEE'D	Fuel type :	DIESEL
Object nr. :	47822	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	DALKIA SA<ID>2229924</ID>	Co2:	119g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	CEE'D SW EX ISG EcoDyn.DPF 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1582
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	NOK	[x] BROKEN DOWN / DAMAGED
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	KLÉBER	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	KLÉBER	Tyre :	[x]	OK	[x]	4-6/	Rim :	/ Hubcap : [x] SCRATCHED
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	/ Hubcap : [x] SCRATCHED	
Wheel RES:	[x]	KLÉBER	Tyre :	OK	[x]	>6/	Rim :	/ Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	ROOF/CENTER/RIGHT	OTHER DAMAGES
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE

Interior

[x]	SEAT FL	SCRATCHED
[x]	SEAT REAR RIGHT	STAIN

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	15 LU =72.00 EUR	0 EUR	235.80 EUR	50 %	307.80 EUR
[x]	REAR DOOR/CENTER/RIGHT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR
[x]	REAR LIGHT/RIGHT/CORNER	WINDOW DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	0 EUR		50 %	
[x]	REAR DOOR/LEFT/CENTER	DENT		MET LAKSCHADE	
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	REAR BUMPER	343.20 EUR	50 %	343.20 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	SIERLIJST	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	REAR LIGHT	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
318.35	982.68	90.00	0	0	0	0	0	0	0
159.18	491.34	45.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1391.03	0	1391.03
HOG: 0	BG: 0		NA Deprec. 695.52
			0.00%
			TOTAL 695.52

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/10/2017 Hour : 11:48 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	