

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	68886 KM
<b>File nr. :</b>	1451596	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FIO473 / WF0LXXGCBLDR07540 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	09/07/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	FORD / FOCUS	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	6276	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	SIEMENS INDUSTRY SOFTWARE NV	<b>Co2:</b>	88g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	FOCUS CLIP. ECONetic Trend 88g 105PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	1560
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	105	<b>kW:</b>	77
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :			
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE	
Wheel RES:	[x]	GOODYEAR	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR WINDOW/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	BONNET/CENTER/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	ROOF/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE

### Interior

[x]	BOOT LID IN	SCRATCHED
-----	-------------	-----------

### Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	-------------------------------	---------------------------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	L+R			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
4	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	
[x]	REAR DOOR/CENTER/RIGHT	DENT				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
5	11	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE				
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
3	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR	
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT				
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
6	10 LU =48.00 EUR	308.20 EUR		50 %	356.20 EUR	

[x]	REAR DOOR/RIGHT/REAR		DENT			
		<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
6	10 LU =48.00 EUR	318.35 EUR			50 %	366.35 EUR
[x]	BONNET/CENTER/LEFT		OTHER DAMAGES			
		<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
1	5 LU =24.00 EUR	0 EUR			50 %	24.00 EUR
[x]	FRONT MUDGUARD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
6	0 LU =0.00 EUR	220.18 EUR			50 %	220.18 EUR
[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR	211.80 EUR			50 %	211.80 EUR

## Interior

[x]	ROOF UPHOLSTERY		CUT / TORN			
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>	
1	I 1 i-vab-intv1r-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR		64.32 EUR	
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>	
1	I 1 i-vab-intv1r-02	SUPPL VELOURS REPAIR	18.00 EUR		18.00 EUR	

## Accessories and others

[x]	REARWINDOW WIPER		BROKEN / CRACKED			
		<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
9	1 LU =4.80 EUR	0 EUR			50 %	4.80 EUR

## Others

	HUB CAP REAR RIGHT					
		<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
8	0 LU =0.00 EUR				50 %	
	HUB CAP FR					
		<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
7	0 LU =0.00 EUR				50 %	

<b>Pieces</b>
---------------

Number	Code	Description	Unit price	Depr.	Total
1	1	MOTORISOLATIE	65.00 EUR	50 %	65.00 EUR
2	1	HALF FRONT SPOILER	30.00 EUR	50 %	30.00 EUR
7	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
8	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
9	1	WIPER	35.00 EUR	50 %	35.00 EUR

1	2	3	4	5	6	7	8	9	10
171.32	241.80	308.20	211.80	115.56	942.73	30.00	30.00	39.80	0
126.82	120.90	154.10	105.90	115.56	471.36	15.00	15.00	19.90	0

INNOVATIVE	TRADITIONAL	GENERAL	
197.88	1893.33	0	<b>2091.21</b>
HOG: 0	BG: 0		NA Deprec. 1144.54
			0.00%
			<b>TOTAL 1144.54</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 26/10/2017 <b>Hour :</b> 10:47 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	