

www.vabfleetservices.be Date: 26/10/2017 1/5

D4QHWZ

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 154456 KM File nr. : Mileage start / arrival: 0 / 01452538 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DJH902 / WVWZZZ3CZCE186154 / E-File nr. : First registration: 01/06/2012 Color: VFS-nr.: **BLUE** Make + Model : Fuel type : VOLKSWAGEN / PASSAT **DIESEL** Object nr. : Fuel: 11905 Classification: **Environment Class:** EURO 5 Customer company: Co2: SIMAC NV 116g/km Driver : Remote controls: TISSUE Covering: Number keys: 1[x]Vehicle kind: Seats (minivan): 0 Vehicle type: PASSAT VAR Comfortline 105PK Country registration: **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	



www.vabfleetservices.be Date: 26/10/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FR:	[x] [x]	FIRESTONE DUNLOP	Tyre:	[x]	OK OK	[x]	4-6 / 4-6 /	Rim:	[x]	WHEEL SCRATCHED)	Hubcap: Hubcap:	
Wheel RES:	[x]	FIRESTONE [x]	Tyre : Width	<u> </u>	OK		>6 / ight	Rim :		Туре		Hubcap :	Index
Fron	ıt tyre		215				55			R		16	W
	n trono		215				5.5				W		

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 26/10/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

Ro	dywork \& windows				
[x]	REAR THRESHOLD/LEFT/REAR		SCRATCH WITH PAINT DAMAGE		
[x]	REAR DOOR/RIGHT/CENTER		DENT		
[x]	REAR THRESHOLD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		
x]	FRONT DOOR/RIGHT/CENTER		DENT		
x]	FRONT MUDGUARD/RIGHT/CENTER		DENT		
[x]	ROOF/CENTER/LEFT		OTHER DAMAGES		
nte	erior				
[x]	SEAT FL		SCRATCHED		
[x]	LUGGAGE COVER		SCRATCHED		
[x]	BOOT LID IN		SCRATCHED		
Ac	cessories and others				
	outside mirror righthand side		SCRATCH WITH PAINT DAMAGE		
x]		BLE	SCRATCH WITH PAINT DAMAGE		
x] ST	OUTSIDE MIRROR RIGHTHAND SIDE	BLE	SCRATCH WITH PAINT DAMAGE		
x] ST	OUTSIDE MIRROR RIGHTHAND SIDE	BLE	SCRATCH WITH PAINT DAMAGE DENT		
x] ST	OUTSIDE MIRROR RIGHTHAND SIDE ATUS: NOT ACCEPTAE dywork \& windows	BLE Repair paint - LI		Depr.	Total
x] ST Bo	OUTSIDE MIRROR RIGHTHAND SIDE ATUS: NOT ACCEPTAE dywork \& windows		DENT	Depr. 50 %	
ST Bo x]	OUTSIDE MIRROR RIGHTHAND SIDE ATUS: NOT ACCEPTAE dywork \& windows REAR DOOR/CENTER/RIGHT	Repair paint - LI	DENT		
ST 30 x]	OUTSIDE MIRROR RIGHTHAND SIDE ATUS: NOT ACCEPTAE dywork \& windows REAR DOOR/CENTER/RIGHT 1 0 LU =0.00 EUR	Repair paint - LI	DENT New paint - E		
x] ST So x]	OUTSIDE MIRROR RIGHTHAND SIDE ATUS: NOT ACCEPTAE dywork \& windows REAR DOOR/CENTER/RIGHT 1 0 LU =0.00 EUR	Repair paint - LI 301.68 EUR	DENT New paint - E SCRATCH WITH PAINT DAMAGE	50 %	301.68 EUR Total
ST Bo x]	OUTSIDE MIRROR RIGHTHAND SIDE TATUS: NOT ACCEPTAE dywork \& windows REAR DOOR/CENTER/RIGHT 1 0 LU =0.00 EUR REAR MUDGUARD/LEFT/CENTER	Repair paint - LI 301.68 EUR Repair paint - LI	DENT New paint - E SCRATCH WITH PAINT DAMAGE	50 % Depr.	301.68 EUR Total
ST So x]	OUTSIDE MIRROR RIGHTHAND SIDE CATUS: NOT ACCEPTAE dywork \& windows REAR DOOR/CENTER/RIGHT 1 0 LU =0.00 EUR REAR MUDGUARD/LEFT/CENTER 2 0 LU =0.00 EUR	Repair paint - LI 301.68 EUR Repair paint - LI	DENT New paint - E SCRATCH WITH PAINT DAMAGE New paint - E	50 % Depr.	301.68 EUR Total
x] ST So x]	OUTSIDE MIRROR RIGHTHAND SIDE CATUS: NOT ACCEPTAE dywork \& windows REAR DOOR/CENTER/RIGHT 1 0 LU =0.00 EUR REAR MUDGUARD/LEFT/CENTER 2 0 LU =0.00 EUR	Repair paint - LI 301.68 EUR Repair paint - LI 308.20 EUR	DENT New paint - E SCRATCH WITH PAINT DAMAGE New paint - E DENT	50 % Depr. 50 %	Total 308.20 EUR
[x] Bo [x]	OUTSIDE MIRROR RIGHTHAND SIDE CATUS: NOT ACCEPTAE dywork \& windows REAR DOOR/CENTER/RIGHT 1 0 LU =0.00 EUR REAR MUDGUARD/LEFT/CENTER 2 0 LU =0.00 EUR FRONT MUDGUARD/LEFT/FRONT	Repair paint - LI 301.68 EUR Repair paint - LI 308.20 EUR Repair paint - LI	DENT New paint - E SCRATCH WITH PAINT DAMAGE New paint - E DENT	50 % Depr. 50 % Depr.	301.68 EUR Total 308.20 EUR
^[x]	OUTSIDE MIRROR RIGHTHAND SIDE CATUS: NOT ACCEPTAE dywork \& windows REAR DOOR/CENTER/RIGHT 1 0 LU =0.00 EUR REAR MUDGUARD/LEFT/CENTER 2 0 LU =0.00 EUR FRONT MUDGUARD/LEFT/FRONT 4 5 LU =24.00 EUR	Repair paint - LI 301.68 EUR Repair paint - LI 308.20 EUR Repair paint - LI	DENT New paint - E SCRATCH WITH PAINT DAMAGE New paint - E DENT New paint - E	50 % Depr. 50 % Depr.	301.68 EUR Total 308.20 EUR



www.vabfle	etservices.be					Date :	26/10/2017	26/10/2017 4/5			
[x] FRONT	BUMPER/LEFT/S	IDE			SCRATCH WITH	H PAINT DAMAG	Έ				
			Repair pain	t - LI	New paint - E		Depr.		Total		
4 0 LU =0	0.00 EUR		211.80 EUR				50 %		211.80 EUR		
Interior											
[x] SEAT F	REAR L				STAIN						
Numbe	r Code		Description			Unit pr	rice Depr.		Total		
5 I 1	i-vab-rein-07		CLEANING	(PER 15')		14.58 E	UR		14.58 EUR		
1	2	3	4	5	6	7	8	9	10		
301.68	308.20	338.08	455.98	14.58	0	0	0	0	0		
150.84	154.10	169.04	227.99	14.58	0	0	0	0	0		
INNO	OVATIVE	TRADI	TIONAL		GENERAL						
	14.58	140	03.94		0				1418.52		
Н	OG: 0	В	G: 0			NA De _l	orec.		716.55		

0.00% TOTAL

716.55



www.vabfleetservices.be Date: 26/10/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMS'	TANCES		NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time: 0 min Reason:		Towing time : Reason :	0 min			
NOT EXECUTED : Reason :	No							
Remark:								
Prices in EUR w	vithout VAT							
Authorized by customer :			Executed by VAB Flee	t Services				
Remark authorized	customer :							
Date : Company :	26/10/2017	Hour: 12:15						
Executed by VAB Fl Services	leet							
E-Mail :	@							
Signature authorized	by customer							