

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: DIRTY [x]
<b>Owner :</b>		<b>Mileage :</b>	51997 KM
<b>File nr. :</b>	1447559	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
HL8294 / WBAXX110800R36573 /		<b>yr of constructionr :</b>	2015 / 10
<b>E-File nr. :</b>		<b>First registration :</b>	20/10/2015
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	BMW / X4	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	
<b>Customer company :</b>	PWC	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	SUV	<b>Engine size:</b>	1995
<b>Gear box :</b>		<b>Number of places:</b>	5
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>	190	<b>kW:</b>	140
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1: OK [x]	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher :
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL: [x] PIRELLI Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RL : [x] PIRELLI Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel FR : [x] PIRELLI Tyre : [x] OK [x] 4-6/ Rim : / Hubcap :
Wheel RR : [x] PIRELLI Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	17	M+S
Rear tyre	225	60	R	17	M+S

Remark :

## Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/CORNER/BELOW	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/LEFT	DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE												
		<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>3 0 LU =0.00 EUR</td> <td>254.16 EUR</td> <td></td> <td>50 %</td> <td>254.16 EUR</td> </tr> </tbody> </table>		Repair paint - LI	New paint - E	Depr.	Total	3 0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR		
	Repair paint - LI	New paint - E	Depr.	Total										
3 0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR										
[x]	REAR LIGHT/LEFT	HOLE/CRACK/TORN												
		<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>4 0 LU =0.00 EUR</td> <td>0 EUR</td> <td></td> <td>50 %</td> <td></td> </tr> </tbody> </table>		Repair paint - LI	New paint - E	Depr.	Total	4 0 LU =0.00 EUR	0 EUR		50 %			
	Repair paint - LI	New paint - E	Depr.	Total										
4 0 LU =0.00 EUR	0 EUR		50 %											
[x]	REAR DOOR/LEFT/REAR	DENT	2X, 1 AANVAARD											
		<table border="1"> <thead> <tr> <th>Number</th> <th>Code</th> <th>Description</th> <th>Unit price</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>I 1 i-vab-uitd-01</td> <td>BEAT OUT DENT</td> <td>63.00 EUR</td> <td></td> <td>63.00 EUR</td> </tr> </tbody> </table>	Number	Code	Description	Unit price	Depr.	Total	2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
Number	Code	Description	Unit price	Depr.	Total									
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR									
[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	HOES											
		<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>1 0 LU =0.00 EUR</td> <td>0 EUR</td> <td></td> <td>50 %</td> <td></td> </tr> </tbody> </table>		Repair paint - LI	New paint - E	Depr.	Total	1 0 LU =0.00 EUR	0 EUR		50 %			
	Repair paint - LI	New paint - E	Depr.	Total										
1 0 LU =0.00 EUR	0 EUR		50 %											

### Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	BROKEN / CRACKED										
		<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>5 0 LU =0.00 EUR</td> <td>0 EUR</td> <td></td> <td>50 %</td> <td></td> </tr> </tbody> </table>		Repair paint - LI	New paint - E	Depr.	Total	5 0 LU =0.00 EUR	0 EUR		50 %	
	Repair paint - LI	New paint - E	Depr.	Total								
5 0 LU =0.00 EUR	0 EUR		50 %									

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
1	1	HOES	40.00 EUR	50 %	40.00 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	REAR LIGHT	108.00 EUR	50 %	108.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	PINKER SPIEGEL	60.00 EUR	50 %	60.00 EUR

1	2	3	4	5	6	7	8	9	10
54.58	63.00	254.16	108.00	60.00	0	0	0	0	0
34.58	63.00	127.08	54.00	30.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
77.58	462.16	0	<b>539.74</b>
HOG: 0	BG: 2		NA Deprec. 308.66
			0.00%
			<b>TOTAL 308.66</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<p><b>Authorized by customer :</b></p> <p><b>Remark authorized customer :</b> KLANT HHEFT HERSTELLING LATEN DOEN AAN ACHTERBUMPER EN ZE HADDEN HET ACHTERLICHT NIET IN VOORRAAD.</p> <p><b>Date :</b> 13/10/2017      <b>Hour :</b> 10:25</p> <p><b>Company :</b></p> <p><b>Executed by VAB Fleet Services</b></p> <p><b>E-Mail :</b> @</p>	<p>Executed by VAB Fleet Services</p>
<p>Signature authorized by customer</p> 	