

www.vabfleetservices.be Date: 31/10/2017 1/5

D5AMLT

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner:		Mileage :	153223 KM
File nr. :	1452980	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FMB022 / WBA5J31030D06	7622 /	yr of constructionr :	/
E-File nr. :		First registration :	13/08/2013
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 5 TOURING	Fuel type :	DIESEL
Object nr. :	12290	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	ALKEN MAES NV	Co2:	134g/km
Driver :		Remote controls:	2
Covering:	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	5 TOURING 520dA 163PK Aut.	Country registration :	BELGIUM

Variant car:	BREAK	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
нр:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	

Metallic paint:

Yes



www.vabfleetservices.be Date: 31/10/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

		[x]	Width	Ì	Но	ight	i		Type		Rim	Index	¬
Wheel RES:	[x]		Tyre:	OK		/	Rim:				/ Hubcap:		
Wheel RR:	[x]	GOODYEAR	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:		
Wheel FR:	[x]	GOODYEAR	$\mathbf{Tyre}: [\mathbf{x}]$	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:		
Wheel RL:	[x]	GOODYEAR	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:		
Wheel FL:	[x]	GOODYEAR	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:		

[x]	Width	Height	Type	Rim	Index
Front tyre	245	45	R	18	W
Rear tyre	245	45	R	18	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



2 0 LU =0.00 EUR

APPRAISAL

31/10/2017 Date: www.vabfleetservices.be 3/5

	ATUS: ACCEPTABLE /	USAGE DAMA	\GE					
Во	dywork \& windows							
x]	REAR MUDGUARD/LEFT/CENTER		SCRATCH (WITHOUT PAINT D.	AMAGE)				
x]	REAR DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAG	GE				
x]	FRONT DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAG	SCRATCH WITH PAINT DAMAGE				
[x]	FRONT MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE					
ST	ATUS: NOT ACCEPTA	BLE						
Во	dywork \& windows							
[x] REAI	REAR BUMPER/CENTER/RIGHT		DENT					
		Repair paint - LI	New paint - E	Depr.	Total			
	3 0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR			
[x]	REAR DOOR/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE					
		Repair paint - LI	New paint - E	Depr.	Total			
	5 0 LU =0.00 EUR	362.02 EUR		50 %	362.02 EUR			
[x]	ROOF/FRONT/LEFT/CENTER		OTHER DAMAGES	CHEMISCHE IN	WERKING			
		Repair paint - LI	New paint - E	Depr.	Total			
	4 0 LU =0.00 EUR	577.80 EUR		50 %	577.80 EUR			
[x]	BONNET/CENTER/LEFT		OTHER DAMAGES	MARTER				
		Repair paint - LI	New paint - E	Depr.	Total			
	1 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR			
[x]	FRONT BUMPER/CENTER/RIGHT		DENT					
		Repair paint - LI	New paint - E	Depr.	Total			

	Pieces					
•	Number	Code	Description	Unit price	Depr.	Total
	1 1	ISOLATIE		50.00 EUR	50 %	50.00 EUR

50 %

254.16 EUR

254.16 EUR

1	2	3	4	5	6	7	8	9	10
74.00	254.16	254.16	577.80	362.02	0	0	0	0	0
37.00	127.08	127.08	288.90	181.01	0	0	0	0	0



www.vabfleetservices.be Date: 31/10/2017 4/5

INNOVATIVE	TRADITIONAL	GENERAL		
0	1522.14	0		1522.14
HOG: 0	BG: 2		NA Deprec.	761.07
			0.00%	
			TOTAL	761.07



www.vabfleetservices.be Date: 31/10/2017 5/5

[x] = Status Modification

Pictures: No)								
CIRCUMS'	TANCES		NORMAL CONCLUSION						
Extra Time :	0 min		Waiting time: 0 min Reason:		Towing time : Reason :	0 min			
NOT EXECUTED :	No				<u> </u>				
Remark:									
Prices in EUR w	vithout VAT								
Authorized by customer:				Executed by VAB Fle	et Services				
Remark authorized	customer :								
Date :	31/10/2017	Hour :	10:59						
Company:									
Executed by VAB Fl Services	leet								
E-Mail :	@								
Signature authorized	by customer								