

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: DIRTY [x] |
| Owner : | | Mileage : | 53526 KM |
| File nr. : | 1447577 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| HL8291 / WBAXX110800R36363 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 16/10/2015 |
| VFS-nr. : | | Color : | BLACK |
| Make + Model : | BMW / X4 | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | | Environment Class: | |
| Customer company : | PWC | Co2: | g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------------|----------------------------|---------|
| VAT over the margin - car: | | Metallic paint: | Yes |
| Variant car: | | Engine size: | 1995 |
| Gear box : | Automaat algemeen | Number of places: | 5 |
| Number of gears: | | Number of doors: | 5 |
| HP: | 190 | kW: | 140 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |
| General condition: | | | |

| | | | |
|------------------------------|--------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | [x] |
| Cert. of reg. / Part 1: | OK [x] | Cert. of conformity : | |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | |
| Warning vest : | OK [x] | Transport licence : | |
| Tax certificate : | | Navigation CD/SD/DVD | |
| Fuel card : | | Car radio : | OK [x] |
| Mobile phone kit : | | Extinguisher : | OK [x] |
| First aid kit : | OK [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | | Oil level : | OK [x] |
| | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | |
|------------|-----|--------|--------|-----|-----|------|-------|-------|-------------------------------|----------|
| Wheel FL: | [x] | DUNLOP | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : | |
| Wheel RL : | [x] | DUNLOP | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : | |
| Wheel FR : | [x] | DUNLOP | Tyre : | [x] | OK | [x] | 4-6/ | Rim : | / | Hubcap : |
| Wheel RR : | [x] | DUNLOP | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : | |
| Wheel RES: | [x] | | Tyre : | OK | / | | Rim : | [x] | MISSING/INCOMPLETE / Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225 | 60 | R | 17 | V |
| Rear tyre | 225 | 60 | R | 17 | V |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] WINDSCREEN/RIGHT WINDOW DAMAGE

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-----------------|---------------|-----------|-----------|
| 1 | I 1 | i-vab-herstr-01 | WINDOW REPAIR | 58.80 EUR | 58.80 EUR |

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE BROKEN / CRACKED

| | Repair paint - LI | New paint - E | Depr. | Total |
|---|-------------------|---------------|-------|-----------|
| 2 | 10 LU =48.00 EUR | 0 EUR | 50 % | 48.00 EUR |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|------------|
| 2 | 1 | MIRROR | 144.00 EUR | 50 % | 144.00 EUR |
| Number | Code | Description | Unit price | Depr. | Total |
| 2 | 1 | INDICATOR | 18.00 EUR | 50 % | 18.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|--------|---|---|---|---|---|---|---|----|
| 58.80 | 210.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 58.80 | 105.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 58.80 | 210.00 | 0 | 268.80 |
| HOG: 0 | BG: 2 | | NA Deprec. 163.80 |
| | | | 0.00% |
| | | | TOTAL 163.80 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE VERY DIRTY

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|--|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 26/10/2017 Hour : 09:09 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |