

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	61152 KM
File nr. :	1447486	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
GL9594 / WBA4E91040G390742 /		yr of constructionr :	/
E-File nr. :		First registration :	01/10/2015
VFS-nr. :		Color :	SILVER
Make + Model :	BMW / 4 GRAN COUPÉ	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	PWC	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	420D	Country registration :	LUXEMBOURG

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	COUPE	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	190	kW:	140
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	NOK
Cert. of reg. copy / Part 2:	NOK	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x] OK [x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	W
Rear tyre	225	50	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/LEFT/FRONT	DENT	
[x]	REAR THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	IN
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	IN
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	BORD PORTE
[x]	THRESHOLD FRONT/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	IN
[x]	FRONT DOOR/LEFT/FRONT	DENT	
[x]	FRONT DOOR/RIGHT/FRONT	DENT	
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	G/D
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	G/D SOUS BASSEMENT

Interior

[x]	DOOR IN REAR L	SCRATCHED
[x]	BOOT LID IN	SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT BUMPER/RIGHT	HOLE/CRACK/TORN	ANTIBROUILLARD
		Repair paint - LI	New paint - E
		Depr.	Total
1	0 LU =0.00 EUR	0 EUR	50 %
		Repair paint - LI	New paint - E
		Depr.	Total
1	5 LU =24.00 EUR	0 EUR	50 % 24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FOG LAMP	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
114.00	0	0	0	0	0	0	0	0	0
57.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	114.00	0	114.00
HOG: 0	BG: 0		NA Deprec. 57.00
			0.00%
			TOTAL 57.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 14:22 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	