

www.vabfleetservices.be Date: 31/10/2017 1/4

D77NO7

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	117163 KM
File nr. :	1454551	Mileage start / arrival:	0/0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FQD640 / WAUZZZ8RXEA	034854 /	yr of constructionr :	/
E-File nr. :		First registration :	20/09/2013
VFS-nr. :		Color :	BLACK
Make + Model :	AUDI / Q5	Fuel type :	DIESEL
Object nr. :	34228	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company:	VACATURE CVBA	Co2:	139g/km
Driver :		Remote controls:	2
Covering:	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	Q5 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			



31/10/2017 Date: www.vabfleetservices.be 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOO	DYEAR	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RL:	[x]	GOO	DYEAR	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FR:	[x]	GOO	DYEAR	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RR:	[x]	GOO	DYEAR	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RES:	[x]			Tyre:		OK		/	Rim:		/	Hubcap:	
		_											
		[x]	,	Width			He	ight		Type		Rim	Index
Fron	t tyre			235			6	55		R		17	W

	[x]	Width	Height	Туре	Rim	Index
From	nt tyre	235	65	R	17	W
Rea	ar tyre	235	65	R	17	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 31/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR MUDGUARD/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR MUDGUARD/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] WINDSCREEN/CENTER/RIGHT WINDOW DAMAGE HERSTELD

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

Repair paint - LI

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR

[x] BONNET/CENTER/LEFT/FRONT OTHER DAMAGES CHEMISCHE INWERKING

1 0 LU =0.00 EUR 348.09 EUR 50 % 348.09 EUR

New paint - E

1	2	3	4	5	6	7	8	9	10
348.09	382.02	0	0	0	0	0	0	0	0
174.04	191.01	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	730.11	0		730.11
HOG: 0	BG: 2		NA Deprec.	365.06
			0.00%	

TOTAL 365.06

Depr.

Total



www.vabfleetservices.be Date: 31/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS'		NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time: 0 mi Reason:	n	Towing time : Reason :	0 min		
NOT EXECUTED : Reason :	No	I		l			
Remark :							
Prices in EUR w	ithout VAT						
Authorized by customer :			Executed by VAB Fleet Se	rvices			
Remark authorized o	customer :						
Date :	31/10/2017	Hour: 15:46					
Company:							
Executed by VAB Fl Services	eet						
E-Mail :	@						
Signature authorized b	by customer						