

D5WXQX

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	146404 KM
File nr. :	1453472	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ENU581 / WAUZZZ8P6DA058694 /		yr of constructionr :	/
E-File nr. :		First registration :	01/02/2013
VFS-nr. :		Color :	BLACK
Make + Model :	AUDI / A3	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	NESTLE BELGILUX NV	Co2:	102g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A3 SB TDie Attract.Start/Stop DPF 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	Yes	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	FIRESTONE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	FIRESTONE	Tyre :	[x]	OK	[x]	4-6/	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
[x]	BONNET/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN		
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS			

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR

[x]	WINDSCREEN/CENTER/LEFT	HOLE/CRACK/TORN		HERSTELD		
	Number	Code	Description	Unit price	Depr.	Total
0	0					

[x]	WINDSCREEN/CENTER/RIGHT	HOLE/CRACK/TORN		HERSTELD		
	Number	Code	Description	Unit price	Depr.	Total
0	0					

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 3	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		43.74 EUR

1	2	3	4	5	6	7	8	9	10
43.74	169.44	0	0	0	0	0	0	0	0
43.74	84.72	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
43.74	169.44	0	213.18
HOG: 0	BG: 1		NA Deprec. 128.46
			0.00%
			TOTAL 128.46

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 02/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	