

D4W30S

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	53477 KM
File nr. :	1452650	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1NHT804 / WAUZZZF45GA057632 /		yr of constructionr :	/
E-File nr. :		First registration :	29/02/2016
VFS-nr. :		Color :	BLUE
Make + Model :	AUDI / A4	Fuel type :	DIESEL
Object nr. :	63890	Fuel :	
Classification :	G	Environment Class:	EURO 6
Customer company :	ELEMENT61 NV	Co2:	104g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6/	Rim :	/
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]	PIRELLI	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	H
Rear tyre	225	50	R	17	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/FRONT	DENT
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS
[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE

Interior

[x]	SEAT FL	SCRATCHED
-----	---------	-----------

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH (WITHOUT PAINT DAMAGE)
-----	-------------------------------	--------------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	L+R		
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	FRONT DOOR/LEFT/REAR	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

1	2	3	4	5	6	7	8	9	10
211.80	318.35	0	0	0	0	0	0	0	0
105.90	159.18	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	530.15	0	530.15
HOG: 0	BG: 0		NA Deprec. 265.08
			0.00%
			TOTAL 265.08

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/10/2017 Hour : 16:06 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	