

D7S3J4

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	159306 KM
<b>File nr. :</b>	1455008	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FVA288 / WBA3Y11070D374962 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	04/11/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	BMW / 3	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	NICONCEPTS	<b>Co2:</b>	127g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	3 GRAN TURISMO 318dA 136PK Aut.	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1995
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	5
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>	136	<b>kW:</b>	100
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK		Service manual :		
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK	[x]
Jack, wheelspanner :			Oil level :	OK	[x]
			Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	Tyre :	OK	/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :			/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	18	W
Rear tyre	225	50	R	18	W

Remark :

## Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :			/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :			/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :			/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :			/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :			/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE		
[x]	FRONT BUMPER/RIGHT/SIDE	WINDOW DAMAGE		
[x]	REAR DOOR/LEFT/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN	

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
<b>3</b>	<b>0 LU =0.00 EUR</b>	<b>211.80 EUR</b>		<b>50 %</b>
				<b>211.80 EUR</b>
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	+ 2 DEUKEN	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
<b>4</b>	<b>0 LU =0.00 EUR</b>	<b>308.20 EUR</b>		<b>50 %</b>
				<b>308.20 EUR</b>
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	+DEUK	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
<b>2</b>	<b>0 LU =0.00 EUR</b>	<b>318.35 EUR</b>		<b>50 %</b>
				<b>318.35 EUR</b>
[x]	FRONT MUDGUARD/LEFT/FRONT	OTHER DAMAGES	SLECHTE HERSTELLING	
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>
	<b>0</b>	<b>0</b>		<b>Depr.</b>
				<b>Total</b>

### Others

RIM FRONT LEFT				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>
	<b>1</b>	<b>I 1</b>	<b>i-vab-herstalu-02</b>	<b>REPAIR ALLOY WHEEL</b>
				<b>95.00 EUR</b>
				<b>95.00 EUR</b>
RIM REAR LEFT				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>
	<b>1</b>	<b>I 1</b>	<b>i-vab-herstalu-02</b>	<b>REPAIR ALLOY WHEEL</b>
				<b>95.00 EUR</b>
				<b>95.00 EUR</b>
RIM REAR RIGHT				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>
	<b>1</b>	<b>I 1</b>	<b>i-vab-herstalu-02</b>	<b>REPAIR ALLOY WHEEL</b>
				<b>95.00 EUR</b>
				<b>95.00 EUR</b>

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
380.00	318.35	211.80	308.20	0	0	0	0	0	0
380.00	159.18	105.90	154.10	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
380.00	838.35	0	<b>1218.35</b>
HOG: 0	BG: 0		NA Deprec. 799.18
			0.00%
			<b>TOTAL 799.18</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 02/11/2017 <b>Hour :</b> <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b> 	