

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	80341 KM
File nr. :	1447501	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
HL8297 / WBAXX110X00R35862 /		yr of constructionr :	/
E-File nr. :		First registration :	26/10/2015
VFS-nr. :		Color :	BLUE
Make + Model :	BMW / X4	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	PWC	Co2:	g/km
Driver :		Remote controls:	1
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	190	kW:	140
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1: OK [x]	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 4-6/ Rim : / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : [x] MISSING/INCOMPLETE / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	245	50	R	18	WINTER H
Rear tyre	245	50	R	18	WINTER H

Remark : RSC

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] FRONT DOOR/LEFT/CENTER DENT
- [x] FRONT DOOR/LEFT/FRONT DENT
- [x] REAR DOOR/LEFT/LEFT DENT

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 2		NA Deprec. 0
			0.00%
			TOTAL 0

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 09:33 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	