

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 125563 KM |
| File nr. : | 1450997 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| WG1969 / WAUZZZ8K6EA023000 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 15/10/2013 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | AUDI / A4 AVANT | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | | Environment Class: | |
| Customer company : | MULLER&WEGENER SARL | Co2: | g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | A4 AVANT Quattro 143PK | Country registration : | LUXEMBOURG |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1968 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 150 | kW: | 110 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |
| General condition: | | | |

| | | | | |
|-------------------------------------|----|-------------------------|--------------------------------|--------|
| Original registr. number : | | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | OK | [x] | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | [x] |
| Tax certificate : | | | Navigation CD/SD/DVD | |
| Fuel card : | | | Car radio : | OK [x] |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | OK | [x] | Oil level : | OK [x] |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | |
|-------------------|-----|-------------|---------------|-----|-----|------|--------------|--------------|-----------------|-----------------|
| Wheel FL: | [x] | BRIDGESTONE | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : | |
| Wheel RL : | [x] | BRIDGESTONE | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : | |
| Wheel FR : | [x] | BRIDGESTONE | Tyre : | [x] | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RR : | [x] | BRIDGESTONE | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : | |
| Wheel RES: | [x] | ANDERE | Tyre : | OK | [x] | >6/ | Rim : | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|-------------------|-------|--------|------|-----|-------|
| Front tyre | 245 | 40 | R | 18 | Y |
| Rear tyre | 245 | 40 | R | 18 | Y |

Remark :

Wheels and tyres:

| | | | | | | | |
|-------------------|--|---------------|----|---|--------------|---|-----------------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|-------------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE
- [x] REAR THRESHOLD/RIGHT/REAR SCRATCH WITH PAINT DAMAGE SLUITKANT
- [x] WINDSCREEN/CENTER/RIGHT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR DOOR/LEFT/CENTER DENT MET LAKSCHADE

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|------------|
| 1 0 LU =0.00 EUR | 318.35 EUR | | 50 % | 318.35 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|---|---|---|---|---|---|---|---|----|
| 318.35 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 159.18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 0 | 318.35 | 0 | 318.35 |
| HOG: 0 | BG: 0 | | NA Deprec. 159.18 |
| | | | 0.00% |
| | | | TOTAL 159.18 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : DOCS WORDEN NAGESTUURD [x] | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 27/10/2017 Hour : 10:07 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |