

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	45032 KM
<b>File nr. :</b>	1447478	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
HL8303 / WBAXX110900R36517 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	16/10/2015
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	BMW / X4	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	
<b>Customer company :</b>	PWC	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	XDRIVE 20D	<b>Country registration :</b>	LUXEMBOURG

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	SUV	<b>Engine size:</b>	1995
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	190	<b>kW:</b>	140
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	NOK
Cert. of reg. copy / Part 2:	NOK [x]	Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	DUNLOP	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	17	V
Rear tyre	225	60	R	17	V

Remark :

## Wheels and tyres:

Wheel FL:			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:			Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: NOT ACCEPTABLE

### Interior

[x]	DASHBOARD	MISSING/INCOMPLETE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR	0 EUR		50 %	

[x]	BACK SHELF	MISSING/INCOMPLETE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	0 LU =0.00 EUR	0 EUR		50 %	

### Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	BACK SHELF	60.00 EUR	50 %	60.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	GARNITURE	15.00 EUR	50 %	15.00 EUR

1	2	3	4	5	6	7	8	9	10
60.00	15.00	0	0	0	0	0	0	0	0
30.00	7.50	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	75.00	0	<b>75.00</b>
HOG: 0	BG: 2		<b>NA Deprec. 37.50</b>
			<b>0.00%</b>
			<b>TOTAL 37.50</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<p><b>Authorized by customer :</b></p> <p><b>Remark authorized customer :</b> GARNITURE DIAGNOSTIQUE MANCO/ DOMMAGE SIGNALE A BMW LAISSE SANS SUITE+PLAGE ARRIERE SERA REMIS AVANT ENLEVEMENT</p> <p><b>Date :</b> 13/10/2017      <b>Hour :</b> 10:04</p> <p><b>Company :</b></p> <p><b>Executed by VAB Fleet Services</b></p> <p><b>E-Mail :</b> @</p>	<p>Executed by VAB Fleet Services</p>
<p>Signature authorized by customer</p> 	