

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	184767 KM
<b>File nr. :</b>	1453167	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FSU315 / WF0MXXGBWMDC63473 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	14/10/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	FORD / GALAXY	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	48582	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	SPIE BELGIUM NV/SA	<b>Co2:</b>	139g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	GALAXY Trend Style DPF 136PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	MONOVOLUME	<b>Engine size:</b>	1997
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	7
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	136	<b>kW:</b>	100
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

## Wheels and tyres: Winter tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	>6/	Rim :	[x] WHEEL SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	M+S
Rear tyre	215	60	R	16	M+S

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	WINDOW REAR DOOR/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE

### Interior

[x]	SEAT REAR L	STAIN
-----	-------------	-------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
3	15 LU =72.00 EUR		0 EUR		50 %
					72.00 EUR
[x]	REAR LIGHT/RIGHT	HOLE/CRACK/TORN			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
3	5 LU =24.00 EUR		0 EUR		50 %
					24.00 EUR
[x]	REAR DOOR/RIGHT/RIGHT	DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
3	30 LU =144.00 EUR		362.02 EUR		50 %
					506.02 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
4	20 LU =96.00 EUR		369.84 EUR		50 %
					465.84 EUR
[x]	REAR BUMPER/SIDE/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>
					<b>Total</b>
4	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR	
					115.56 EUR

[x]	REAR DOOR/RIGHT/REAR		DENT		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	30 LU =144.00 EUR	382.02 EUR		50 %	526.02 EUR

[x]	FRONT MUDGUARD/LEFT/FRONT		DENT		
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	63.00 EUR

### Interior

[x]	BOOT LID IN		CARVED		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	KOFFERBEKLEDING	100.00 EUR	50 %	100.00 EUR
3	1	REAR BUMPER	411.84 EUR	50 %	411.84 EUR
3	1	REFLECTOR	20.00 EUR	50 %	20.00 EUR
3	1	REAR LIGHT	108.00 EUR	50 %	108.00 EUR

1	2	3	4	5	6	7	8	9	10
124.00	63.00	1141.86	1107.42	0	0	0	0	0	0
62.00	63.00	570.93	611.49	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
178.56	2257.72	0	2436.28
HOG: 0	BG: 2		NA Deprec. 1307.42
			0.00%
			<b>TOTAL 1307.42</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 31/10/2017 <b>Hour :</b> 15:11 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b> 	