

D7UK7B

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	9753 KM
File nr. :	1455060	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1PLA403 / WF0XXXTTGXFU01833 /		yr of constructionr :	/
E-File nr. :		First registration :	29/07/2016
VFS-nr. :		Color :	GREY
Make + Model :	FORD / TRANSIT	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	DELIVERY VAN B	Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	212g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	2198
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	5
HP:	155	kW:	114
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	235	65	R	16	H
Rear tyre	235	65	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/RIGHT/CENTER DENT

Accessories and others

[x] VEH COVERED WITH STICKERS STICKER(S)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

[x] REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	158.85 EUR		50 %	158.85 EUR

[x] REAR MUDGUARD/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR

[x] ROOF/CENTER/RIGHT DENT

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	361.13 EUR		50 %	361.13 EUR

[x] ROOF STYLE/FRONT/RIGHT/FRONT DENT

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Accessories and others

[x] OUTSIDE MIRROR LEFTHAND SIDE BROKEN / CRACKED

	Repair paint - LI	New paint - E	Depr.	Total
4 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 5 specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		72.90 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	INDICATOR	25.00 EUR	50 %	25.00 EUR

1	2	3	4	5	6	7	8	9	10
72.90	231.15	269.49	49.00	424.13	0	0	0	0	0
72.90	115.58	190.06	24.50	243.56	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
246.54	800.13	0	1046.67
HOG: 0	BG: 3		NA Deprec. 646.60
			0.00%
			TOTAL 646.60

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 30/10/2017 Hour : 16:20 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	