

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	65211 KM
<b>File nr. :</b>	1447575	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
HL8987 / WBAXX110600R35504 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	26/10/2015
<b>VFS-nr. :</b>		<b>Color :</b>	BLUE
<b>Make + Model :</b>	BMW / X4	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	
<b>Customer company :</b>	PWC	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1995
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	5
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>	190	<b>kW:</b>	140
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	
Mobile phone kit :		Extinguisher :	
First aid kit :		Warning triangle :	
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Winter tires

Wheel FL:	[x] PIRELLI	Tyre :	OK [x] 4-6/	Rim :		Hubcap :	
Wheel RL :	[x] PIRELLI	Tyre :	OK [x] 4-6/	Rim :		Hubcap :	
Wheel FR :	[x] PIRELLI	Tyre :	[x] OK [x] 4-6/	Rim :		Hubcap :	
Wheel RR :	[x] PIRELLI	Tyre :	OK [x] 4-6/	Rim :		Hubcap :	
Wheel RES:	[x]	Tyre :	OK /	Rim :	[x] MISSING/INCOMPLETE	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	17	WINTER H
Rear tyre	225	60	R	17	WINTER H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :		Hubcap :	
Wheel RL :		Tyre :	OK /	Rim :		Hubcap :	
Wheel FR :		Tyre :	OK /	Rim :		Hubcap :	
Wheel RR :		Tyre :	OK /	Rim :		Hubcap :	
Wheel RES:		Tyre :	OK /	Rim :		Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- |     |                            |                           |            |
|-----|----------------------------|---------------------------|------------|
| [x] | REAR BUMPER/LEFT/LEFT      | SCRATCH WITH PAINT DAMAGE | SPOILER    |
| [x] | ROOF/FRONT/CENTER/RIGHT    | CHIPS                     |            |
| [x] | FRONT MUDGUARD/RIGHT/FRONT | DENT                      | /STEENSLAG |

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	<b>0</b>
HOG: 0	BG: 2		NA Deprec. 0
			0.00%
			<b>TOTAL 0</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 26/10/2017 <b>Hour :</b> 08:49 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	