

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	59993 KM
File nr. :	1447475	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
GL9615 / WBA4E91080G286352 /		yr of constructionr :	2015 / 10
E-File nr. :		First registration :	02/10/2015
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 4 GRAN COUPÉ	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	PWC	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	190	kW:	140
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1: OK [x]	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher :
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] BRIDGESTONE Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel FR : [x] BRIDGESTONE Tyre : [x] OK [x] 4-6/ Rim : / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	W
Rear tyre	225	50	R	17	W

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	DENT	2X
[x]	REAR DOOR/RIGHT/FRONT	DENT	2X
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES	SLECHTE HERSTELLING

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	DENT	2X		
3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	63.00 EUR	
3	I 1 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR	19.80 EUR	
[x]	FRONT DOOR/LEFT/CENTER	DENT	ENKELE		
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	382.02 EUR	50 %	382.02 EUR	
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	254.16 EUR	50 %	254.16 EUR	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FOG LAMP	108.00 EUR	50 %	108.00 EUR

1	2	3	4	5	6	7	8	9	10
362.16	382.02	82.80	0	0	0	0	0	0	0
181.08	191.01	82.80	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
82.80	744.18	0	826.98
HOG: 0	BG: 0		NA Deprec. 454.89
			0.00%
			TOTAL 454.89

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 10:30 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	