

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	64539 KM
File nr. :	1447488	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
GL9614 / WBA4E91030G286467 /		yr of constructionr :	/
E-File nr. :		First registration :	16/10/2015
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 4	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	PWC	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	190	kW:	140
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :		
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK [x]	Warning triangle :	OK	[x]
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	1.6-2/	Rim :	/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	1.6-2/	Rim :	/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	[x]	MISSING/INCOMPLETE / Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	45	R	18	WINTER V
Rear tyre	225	45	R	18	WINTER V

Remark : RSC

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] FRONT DOOR/LEFT/CENTER DENT
- [x] ROOF STYLE/FRONT/LEFT/CENTER DENT
- [x] FRONT DOOR/RIGHT/CENTER DENT
- [x] BONNET/CENTER/LEFT/FRONT CHIPS

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 2		NA Deprec. 0
			0.00%
			TOTAL 0

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 09:09 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	