

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	52204 KM
File nr. :	1448586	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HLF927 / WDD1760121V020662 /		yr of constructionr :	/
E-File nr. :		First registration :	19/08/2014
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / A	Fuel type :	DIESEL
Object nr. :	45730	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KPMG TAX AND LEGAL ADVISERS	Co2:	92g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :			
Wheel FR :	[x]	DUNLOP	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	T
Rear tyre	195	65	R	15	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE	+DEUK		
		Repair paint - LI	New paint - E	Depr.	Total	
5	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	
[x]	ROOF/CENTER/RIGHT		OTHER DAMAGES	CHEM. INWERKING		
		Repair paint - LI	New paint - E	Depr.	Total	
7	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR	
[x]	FRONT DOOR/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE	+DEUK		
		Repair paint - LI	New paint - E	Depr.	Total	
6	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR	
[x]	BONNET/CENTER/LEFT		OTHER DAMAGES	CHEM. INWERKING		
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR	
[x]	FRONT MUDGUARD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
6	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR	
[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 6	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	87.48 EUR

HUB CAP FL

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
87.48	90.00	211.80	290.08	211.80	538.53	481.50	0	0	0
87.48	45.00	105.90	145.04	105.90	269.26	240.75	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
87.48	1823.71	0	1911.19
HOG: 0	BG: 0		NA Deprec. 999.34
			0.00%
			TOTAL 999.34

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/10/2017 Hour : 07:36 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	