

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	99679 KM
File nr. :	1454207	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GQI737 / WDD2120051B000894 /		yr of constructionr :	/
E-File nr. :		First registration :	01/04/2014
VFS-nr. :		Color :	BLACK
Make + Model :	MERCEDES / E	Fuel type :	DIESEL
Object nr. :	11380	Fuel :	
Classification :	L	Environment Class:	EURO 5
Customer company :	IMEC VZW	Co2:	127g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	2143
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	NOK [x] MISSING/INCOMPLETE
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x] MICHELIN	Tyre :	OK [x] >6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :	
Wheel RL :	[x] MICHELIN	Tyre :	OK [x] 2-4/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :	
Wheel FR :	[x] MICHELIN	Tyre :	[x] OK [x] >6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :	
Wheel RR :	[x] MICHELIN	Tyre :	OK [x] 2-4/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :	
Wheel RES:	[x] MICHELIN	Tyre :	OK [x] >6/	Rim :		/ Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	245	45	R	17	W
Rear tyre	245	45	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel RL :		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel FR :		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel RR :		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel RES:		Tyre :	OK /	Rim :		/ Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR DOOR/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR MUDGUARD/RIGHT/FRONT DENT
- [x] REAR DOOR/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)
- [x] BONNET/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
1	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR	
[x]	WINDSCREEN/CENTER/RIGHT		WINDOW DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstr-02	SUPPL WINDOW REPAIR	29.40 EUR		29.40 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	CHROOM	25.00 EUR	50 %	25.00 EUR

1	2	3	4	5	6	7	8	9	10
279.16	88.20	0	0	0	0	0	0	0	0
139.58	88.20	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
88.20	279.16	0	367.36
HOG: 0	BG: 2		NA Deprec. 227.78
			0.00%
			TOTAL 227.78

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 31/10/2017 Hour : 12:17 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	