

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	148624 KM
File nr. :	1453793	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1AII797 / WV1ZZZ2KZAX127290 /		yr of constructionr :	/
E-File nr. :		First registration :	17/01/2011
VFS-nr. :		Color :	WHITE
Make + Model :	VOLKSWAGEN / CADDY	Fuel type :	DIESEL
Object nr. :	30727	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	K-BORINGEN NV	Co2:	159g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	CADDY 5d 2.0SDi 5v 70PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	1968
Gear box :	Manueel	Number of places:	2
Number of gears:	5	Number of doors:	4
HP:	69	kW:	51
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	NOK [x] MISSING/INCOMPLETE
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK [x]	0-1.6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK [x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK [x]	0-1.6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK [x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]	BRIDGESTONE	Tyre :	OK [x]	4-6/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	T
Rear tyre	195	65	R	15	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :		Hubcap :
Wheel RL :		Tyre :	OK /	Rim :		Hubcap :
Wheel FR :		Tyre :	OK /	Rim :		Hubcap :
Wheel RR :		Tyre :	OK /	Rim :		Hubcap :
Wheel RES:		Tyre :	OK /	Rim :		Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	DENT
[x]	REAR DOOR/CENTER/RIGHT	DENT
[x]	FRONT MUDGUARD/RIGHT/REAR	DENT
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS

Interior

[x]	BOOT LID IN	OTHER DAMAGES
-----	-------------	---------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR
[x]	REAR MUDGUARD/LEFT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
3	5 LU =24.00 EUR	231.15 EUR		50 %	255.15 EUR
[x]	REAR THRESHOLD/RIGHT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
5	5 LU =24.00 EUR	232.88 EUR		50 %	256.88 EUR
[x]	BONNET/CENTER/LEFT	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
6	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	14.58 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR
6	1	ISOLATIE	70.00 EUR	50 %	70.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	110.64	255.15	329.40	256.88	94.00	0	0	0	0
14.58	110.64	127.58	164.70	128.44	47.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
125.22	935.43	0	1060.65
HOG: 0	BG: 3		NA Deprec. 592.94
			0.00%
			TOTAL 592.94

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 31/10/2017 Hour : 15:58 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	