

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	140770 KM
<b>File nr. :</b>	1453803	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1DEO475 / VF37J9HN0CJ584297 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	24/04/2012
<b>VFS-nr. :</b>		<b>Color :</b>	WHITE
<b>Make + Model :</b>	PEUGEOT / PARTNER	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	72417	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	CEGELEC BUILDING SERVICES	<b>Co2:</b>	135g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	PARTNER TEPEE Access 75PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	No
<b>Variant car:</b>	MONOVOLUME	<b>Engine size:</b>	1560
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	5	<b>Number of doors:</b>	4
<b>HP:</b>	75	<b>kW:</b>	55
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

## Wheels and tyres: Winter tires

Wheel FL:	[x]	FULDA	Tyre :	OK	[x]	2-4/	Rim :	[x]	/	Hubcap :	[x]	SCRATCHED
Wheel RL :	[x]	FULDA	Tyre :	OK	[x]	2-4/	Rim :		/	Hubcap :	[x]	SCRATCHED
Wheel FR :	[x]	FULDA	Tyre :	[x]	OK	[x]	2-4/	Rim :		Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	FULDA	Tyre :	OK	[x]	2-4/	Rim :		/	Hubcap :		
Wheel RES:	[x]	FULDA	Tyre :	OK		/	Rim :		/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	225	65	R	15	M+S
Rear tyre	225	65	R	15	M+S

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT MUDGUARD/LEFT/CENTER	DENT
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS

### Interior

[x]	STEERING WHEEL	OTHER DAMAGES
[x]	BOOT LID IN	OTHER DAMAGES

### Accessories and others

[x]	OUTSIDE MIRROR	SCRATCH WITH PAINT DAMAGE
[x]	VEH COVERED WITH STICKERS	STICKER(S)

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	HOLE/CRACK/TORN			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
1	15 LU =72.00 EUR		0 EUR		50 %
					72.00 EUR
[x]	REAR MUDGUARD/LEFT/REAR	DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
2	30 LU =144.00 EUR		231.15 EUR		50 %
					375.15 EUR
[x]	ROOF/CENTER/RIGHT	DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
3	25 LU =120.00 EUR		361.13 EUR		50 %
					481.13 EUR

### Others

	HUB CAP FL				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
4	0 LU =0.00 EUR				50 %

HUB CAP REAR L

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR			50 %	

## Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR

Number	Code	Description	Unit price	Depr.	Total
4	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

Number	Code	Description	Unit price	Depr.	Total
4	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

Number	Code	Description	Unit price	Depr.	Total
4	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

1	2	3	4	5	6	7	8	9	10
329.40	375.15	481.13	67.50	0	0	0	0	0	0
164.70	187.58	240.56	33.75	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1253.18	0	<b>1253.18</b>
HOG: 0	BG: 3		NA Deprec. 626.59
			0.00%
			<b>TOTAL 626.59</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 30/10/2017 <b>Hour :</b> 14:33 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	