

D65AYQ

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	85550 KM
File nr. :	1453674	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EDW386 / VF1KZ1A0747684946 /		yr of constructionr :	/
E-File nr. :		First registration :	01/11/2012
VFS-nr. :		Color :	SILVER
Make + Model :	RENAULT / MEGANE	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC BANK NV	Co2:	104g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	MEGANE GT TomTom Edition 90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	T
Rear tyre	195	65	R	15	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	ROOF/REAR/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT MUDGUARD/LEFT/CENTER	DENT

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE
[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
5	15 LU =72.00 EUR		0 EUR		50 %
					72.00 EUR
[x]	REAR DOOR/CENTER/LEFT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
6	0 LU =0.00 EUR		301.68 EUR		50 %
					301.68 EUR
[x]	REAR LIGHT/RIGHT/CORNER	HOLE/CRACK/TORN			
			Repair paint - LI	New paint - E	Depr.
					Total
9	5 LU =24.00 EUR		0 EUR		50 %
					24.00 EUR
[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
4	0 LU =0.00 EUR		308.20 EUR		50 %
					308.20 EUR
[x]	REAR BUMPER/SIDE/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
7	11 i-vab-sp-01	SPOTREPAIR		115.56 EUR	
					115.56 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
8	0 LU =0.00 EUR		308.20 EUR		50 %
					308.20 EUR

[x]	BONNET/CENTER/RIGHT		DENT			
Number	Code	Description	Unit price	Depr.	Total	
10	I 4 i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		391.20 EUR	

[x]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	

[x]	ROOF/CENTER/LEFT		DENT			
Number	Code	Description	Unit price	Depr.	Total	
10	I 5 i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		489.00 EUR	

Interior

[x]	SEAT FL		CUT / TORN			
		Repair paint - LI	New paint - E	Depr.	Total	
2	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total	
1	I 2 specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		29.16 EUR	

HUB CAP FL

		Repair paint - LI	New paint - E	Depr.	Total	
9	0 LU =0.00 EUR			50 %		

HUB CAP REAR L

		Repair paint - LI	New paint - E	Depr.	Total	
9	0 LU =0.00 EUR			50 %		

HUB CAP REAR RIGHT

		Repair paint - LI	New paint - E	Depr.	Total	
9	0 LU =0.00 EUR			50 %		

HUB CAP FR

		Repair paint - LI	New paint - E	Depr.	Total	
9	0 LU =0.00 EUR			50 %		

Pieces					
Number	Code	Description	Unit price	Depr.	Total
2	1	SEAT UPHOLSTERY TISSUE	120.00 EUR	50 %	120.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	REAR BUMPER	343.20 EUR	50 %	343.20 EUR
Number	Code	Description	Unit price	Depr.	Total
9	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
9	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
9	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
9	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
9	1	REAR LIGHT	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
29.16	240.00	211.80	308.20	415.20	301.68	115.56	308.20	234.00	880.20
29.16	120.00	105.90	154.10	207.60	150.84	115.56	154.10	117.00	880.20

INNOVATIVE	TRADITIONAL	GENERAL	
1024.92	2019.08	0	3044.00
HOG: 0	BG: 0		NA Deprec. 2034.46
			0.00%
			TOTAL 2034.46

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 30/10/2017 Hour : 15:48 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	