

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	30597 KM
File nr. :	1453695	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
YD4014 / VF1BZ140649741907 /		yr of constructionr :	/
E-File nr. :		First registration :	27/08/2014
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / MEGANE	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	B	Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :			
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	GOODYEAR	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	DENT
[x]	REAR DOOR/RIGHT/REAR	DENT
[x]	REAR DOOR/RIGHT/FRONT	DENT
[x]	FRONT DOOR/LEFT/REAR	DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	5 LU =24.00 EUR	211.80 EUR		50 %	235.80 EUR
[x]	REAR THRESHOLD/RIGHT/REAR	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR
[x]	FRONT BUMPER/LEFT/CORNER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

HUB CAP REAR RIGHT

		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	SPOILER	100.00 EUR	50 %	100.00 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	335.80	310.50	30.00	0	0	0	0	0	0
105.90	167.90	155.25	15.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	888.10	0	888.10
HOG: 0	BG: 0		NA Deprec. 444.05
			0.00%
			TOTAL 444.05

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 31/10/2017 Hour : 10:28 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	