

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	193677 KM
File nr. :	1452106	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FTC520 / YV1FS31A1E2293215 /		yr of constructionr :	/
E-File nr. :		First registration :	16/10/2013
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / S60	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	MAQUET BELGIUM NV	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	S60 BER D3 Kinetic 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1984
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	SEMPERIT	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]
Wheel RR :	[x]	SEMPERIT	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	50	R	17	W
Rear tyre	215	50	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR DOOR/RIGHT/FRONT DENT
- [x] WINDSCREEN/CENTER/RIGHT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

		Repair paint - LI	New paint - E	Depr.	Total
[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE		
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	FRONT DOOR/RIGHT/REAR		DENT		
Number	Code	Description	Unit price	Depr.	Total
0	0				

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
190.00	211.80	0	0	0	0	0	0	0	0
190.00	105.90	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
190.00	211.80	0	401.80
HOG: 0	BG: 0		NA Deprec. 295.90
			0.00%
			TOTAL 295.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 02/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	